






report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 1700 CDTI E4
Colour	Red
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	170 Nm at 1.750 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

	-	4	-	-	1
ᆮ	п	ш	ľV	,	1

Lifety 1	
Date	2022-01-13
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

Advice

MOT expiry date	2025-01-17
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	6
Total items failed	5

MOT #15	2024-01-15 09:37
MOT test number	491332346412
Result	✓ Passed
Next expiry date	2025-01-17
Advice Nearside Play in steering rack inner joint(s)	

MOT #14	2023-01-12 10:37
MOT test number	770397676778
Result	✓ Passed
MOT #13	2022-01-18 16:15
MOT test number	484043428405
Result	✓ Passed

MOT #12	2021-07-12 16:13
MOT test number	692317967868
Result	✓ Passed

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #11 2020-12-09 09:24

MOT test number 790674883356

Result ✓ Passed

Advice Nearside Front slight play detected in inner steering rack joint, ok at present, rear silencer outer skin rusted ok at present.

MOT #10 2020-06-13 13:26

MOT test number 173216338666

Result
✓ Passed

MOT #9 2019-03-29 07:25

MOT test number 303312104018

Result \rightarrow Passed

MOT #8 2018-04-10 12:24

MOT test number 959610644460

Result

Passed

MOT #7 2017-04-20 06:55

MOT test number 746712572003

Result ✓ Passed

Advice Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #6 2016-04-22 09:23

MOT test number 175608073616

Result
✓ Passed

MOT #5 2015-04-24 08:26

MOT test number 678064015124

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Fail Nearside Rear coil spring broken (2.4.C.1a)

Fail Steering wheel locking device missing (2.1.6)

Pass with rectification Nearside Headlamp aim too far to the left (1.8)

MOT #3 2014-05-14 13:38

MOT test number 218784934176

Result ✓ Passed

MOT #2

MOT test number

496735233165

Result

Advice
(2.4.G.2)

Nearside Front Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt

MOT test number

Fass with rectification

Offside Headlamp aim too low (1.8)

Pass with rectification

Nearside Headlamp aim too low (1.8)

Advice
(2.4.G.2)

Nearside Front Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	17 January 2025
Full MOT history	See MOT history

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date


Category

Damage 2

Type

Date Category

Туре



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

e when motory	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Download here.	

Plate changes	More info >
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	NIE UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-01-10
Last registration	2024-01-15
Complete history	See info



Registration #1	2011-01-10	21 mi
Registration #2	2013-05-15	14.588 mi
Registration #3	2014-05-14	25.378 mi
Registration #4	2015-04-23	35.601 mi
Registration #5	2015-04-24	35.601 mi
Registration #6	2016-04-22	47.696 mi
Registration #7	2017-04-20	61.745 mi
Registration #8	2018-04-10	73.441 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

77,777 86

CarCheck.co.uk page 11/12



WP60GYZ
report date: 2024-03-28

Safety ratings

NCAP rating	****
-------------	------

Video <u>see crash video</u>



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1210 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	3908524

CarCheck.co.uk page 12/12