



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 LX HDI
Colour	Silver
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-19
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT #25	2021-03-02 12:59
MOT test number	117762649540
Result	✓ Passed
Next expiry date	2022-03-31

MOT #24	2021-03-02 10:15
MOT test number	101740719952
Result	✗ Failed

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Pass with rectification** Nearside Rear Position lamp showing white light to the rear (4.2.3 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #23	2020-03-03 12:05
MOT test number	811852014554
Result	✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing outside edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing outside edge (5.2.3 (e))
- Advice** Offside Front Play in steering rack inner joint(s)

MOT #22	2019-03-05 17:02
MOT test number	147348107746
Result	✓ Passed

- Advice** Offside Front Play in steering rack inner joint(s)

**MOT #21** 2019-03-05 11:08**MOT test number** 244059045571**Result** ✗ Failed**Fail** Offside Rear Position lamp not working (4.2.1 (a))**Fail** Nearside Front Suspension unit leaking (5.3.5 (c))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Play in steering rack inner joint(s)**MOT #20** 2018-03-05 10:22**MOT test number** 524232620264**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #19** 2018-03-05 10:22**MOT test number** 223269222822**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #18** 2017-03-08 15:17**MOT test number** 589167286969**Result** ✓ Passed

**MOT #17**

2016-03-08 16:24

MOT test number

462105811651

Result

✓ Passed

- Advice** Offside Front brake binding slightly
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)
- Advice** Nearside Front tyre wearing on outer edge
- Advice** Offside Side repeater slightly discoloured (1.4.A.2f)

MOT #16

2016-03-08 12:46

MOT test number

820161172219

Result

✗ Failed

- Advice** Offside Front brake binding slightly
- Fail** Offside Stop lamp not working (1.2.1b)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front tyre wearing on outer edge
- Advice** Offside Side repeater slightly discoloured (1.4.A.2f)

MOT #15

2015-03-04 09:44

MOT test number

475943365077

Result

✓ Passed

MOT #14

2015-03-02 15:29

MOT test number

625401765004

Result

✗ Failed

- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #13** 2014-03-12 14:55**MOT test number** 195731674092**Result** ✓ Passed**MOT #12** 2014-03-11 09:52**MOT test number** 308030374033**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #11** 2013-03-12 11:05**MOT test number** 858101073069**Result** ✓ Passed**MOT #10** 2013-03-12 11:05**MOT test number** 878371573049**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #9** 2012-03-06 13:26**MOT test number** 585786162055**Result** ✓ Passed**Advice** Nearside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)**MOT #8** 2012-03-06 13:26**MOT test number** 319746562063**Result** ✗ Failed**Advice** Nearside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)

**MOT #7** 2011-03-07 12:28**MOT test number** 497046761011**Result** ✓ Passed**Notice** Front brake pads low**MOT #6** 2011-03-07 12:28**MOT test number** 935366661032**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Front brake pads low**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #5** 2010-03-08 10:15**MOT test number** 183267860010**Result** ✓ Passed**MOT #4** 2010-03-08 10:15**MOT test number** 951567260030**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2009-03-17 12:08**MOT test number** 702246779057**Result** ✓ Passed



MOT #2	2009-03-17 12:08
MOT test number	773386679019
Result	✗ Failed
Pass with rectification	Offside Front Front position lamp(s) not working (1.1.A.3b)
Pass with rectification	Nearside Front Front position lamp(s) not working (1.1.A.3b)

MOT #1	2008-03-25 09:51
MOT test number	261845288057
Result	✓ Passed
Notice	Nearside front tyre and both rears outer wall perished
Notice	Both rear tyres outer edges unevenly worn



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-03-31
Last registration	2021-03-02
Complete history	See info



Registration #1	2005-03-31	14 mi
Registration #2	2008-03-25	31.778 mi
Registration #3	2009-03-17	42.300 mi
Registration #4	2010-03-08	52.395 mi
Registration #5	2011-03-07	63.627 mi
Registration #6	2012-03-06	74.417 mi
Registration #7	2013-03-12	84.787 mi
Registration #8	2014-03-11	94.821 mi
Registration #9	2014-03-12	94.821 mi
Registration #10	2015-03-02	104.372 mi
Registration #11	2015-03-04	104.374 mi
Registration #12	2016-03-03	114.377 mi
Registration #13	2017-03-02	124.377 mi
Registration #14	2018-03-02	134.377 mi
Registration #15	2019-03-02	144.377 mi
Registration #16	2020-03-02	154.377 mi
Registration #17	2021-03-02	164.377 mi
Registration #18	2022-03-02	174.377 mi
Registration #19	2023-03-02	184.377 mi
Registration #20	2024-03-02	194.377 mi
Registration #21	2025-03-02	204.377 mi
Registration #22	2026-03-02	214.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1475 mm
Length	4745 mm
Wheel base	2750 mm
Max. allowed weight	1944 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JB100007171