





report date: 2024-03-28

General information

Make	AUDI
Model	S5 S5 V8 QUATTRO
Colour	Silver
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	354 BHP
Max. torque	440 Nm at 3.500 rpm
Engine capacity	4.163 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.9 mpg
Consumption extra urban	30.7 mpg
Consumption combined	22.8 mpg
CO2 emission	298 g/km
CO2 label	М



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-05

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-10-07
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	25
Total items failed	8

MOT #20	2023-10-07 09:33
MOT test number	519181214376
Result	✓ Passed
Next expiry date	2024-10-07
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #19		2023-10-07 09:33
MOT test number		752612767784
Result		X Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Oil leak, but not	excessive (8.4.1 (a) (i))	

MOT #18	2022-10-05 08:35
MOT test number	197991553481
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #17	2021-09-29 10:33
MOT test number	995662968000
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #16 2020-10-07 09:52

MOT test number 800177484098

Result
✓ Passed

MOT #15 2020-10-06 08:29

MOT test number 452012909925

Result ★ Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #14 2019-10-08 09:49

MOT test number 329722823824

MOT #13 2019-10-05 12:38

MOT test number 324447941943

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #12 2018-10-02 13:59

MOT test number 444755044786

Result

Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #11 2016-07-01 08:48

MOT test number 764462215034

Result
✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement inner-both arms (2.4.G.2)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement inner-both arms (2.4.G.2)

MOT #10 2016-07-01 08:48

MOT test number 442336030823

Result X Failed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement inner-both arms (2.4.G.2)

Pass with rectification Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement inner-both arms (2.4.G.2)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #9 2015-07-07 15:30

MOT test number 238598085466

Result

Passed

Advice Nearside Inner Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Inner Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Inner Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #8 2015-07-07 15:30

MOT test number 866048085148

Result X Failed

Pass with rectification Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Offside Inner Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Inner Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Inner Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7 2014-03-03 13:45

MOT test number 136922364404

Result ✓ Passed

MOT #6 2014-02-26 15:41

MOT test number 298417554069

Result X Failed

Fail Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2012-11-20 16:01

MOT test number 406285922422

Result × Failed

Pass with rectification Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

CarCheck.co.uk page 6/14



MOT test number

Result

Notice

WU07AXS

report date: 2024-03-28

300891500466

✓ Passed

MOT #4	2012-11-20 16:01
MOT test number	728405622307
Result	✓ Passed
MOT #3	2012-07-27 10:55
MOT test number	178429102215
Result	✓ Passed
MOT #2	2011-07-28 14:37
MOT test number	307539601460
Result	✓ Passed
MOT #1	2010-07-20 14:05

Advice Front Tyre worn close to the legal limit (4.1.E.1)

Nail in offside rear tyre

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	7 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



WU07AXS
report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report J	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	AK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-07-31
Last registration	2023-10-07
Complete history	See info



Registration #1	2007-07-31	7 mi
Registration #2	2010-07-20	14.819 mi
Registration #3	2011-07-28	21.680 mi
Registration #4	2012-07-27	26.501 mi
Registration #5	2012-11-20	27.772 mi
Registration #6	2014-02-26	40.151 mi
Registration #7	2014-03-03	40.267 mi
Registration #8	2015-07-07	59.563 mi
Registration #9	2016-07-01	74.598 mi
Registration #10	2016-07-01	74.598 mi
Registration #11		9.79 es
Registration #12		11.777 es
Registration #13		9.79 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.79 es
Registration #18		11.777 es
Registration #19		D.777 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1854 mm
Height	1372 mm
Length	4625 mm
Wheel base	2751 mm
Kerb weight	1630 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	63 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	CAU 002454

CarCheck.co.uk page 14/14