



General information

Make	MINI
Model	MINI (R60) COOPER D
Colour	White
Year of manufacture	2013
Top speed	112 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 BHP	0 < 101 A
Max. torque	270 Nm at 1.750 rpm	101 - 120 ^B _C
Engine capacity	1.995 cc	121 - 140
Cylinders	4	141 - 165 F
Fuel type	Diesel	166 - 185 H
Consumption city	39.2 mpg	186 - 225
Consumption extra urban	60.1 mpg	225+
Consumption combined	50.4 mpg	
CO2 emission	149 g/km	
CO2 label	F	




Internet history

Entry 1	
Date	2021-07-23
Pictures	19
Listing price	<u>View report</u>









source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-25
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	20
Total items failed	0

MOT #12		2024-02-26 13:37
MOT test	number	825910061381
Result		🗸 Passed
Next expi	ry date	2025-02-25
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Advice	Front reg plate damaged	
Advice	Nearside Front brake wear sensor insecure	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Front coil spring incorrectly mounted	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #11	2023-02-24 09:49
MOT test number	936353067831
Result	✓ Passed
MOT #10	2022-08-04 15:55
MOT test number	244436961753





MOT #9		2021-08-05 16:03
MOT test	number	940641562287
Result		✓ Passed
MOT #8		2021-07-23 10:00
MOT test	number	657810140035
Result		🗙 Failed
MAJOR	Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))	
MAJOR	Front Anti-roll bar pin or bush excessively worn both front (5.3.4 (a) (i))	
MAJOR	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
MAJOR	Offside Front Macpherson strut top bush or bearing has excessive wear or fr	ree play (5.3.4 (a) (i))
MAJOR	Rear Brake disc significantly and obviously worn $(1.1.14 (a) (i))$	
MAJOR	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
MAJOR	Nearside Front Macpherson strut top bush or bearing has excessive wear or	free play (5.3.4 (a) (i))

MOT #7	2020-11-26 10:32
MOT test number	888455895260
Result	✓ Passed
MOT #6	2020-11-25 14:49

MOT test numbe	er 913724107653
Result	× Failed
DANGEROUS (d) (ii))	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3
Advice Near	side Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))





MOT #5		2019-11-20 13:40
MOT test	number	312769564210
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing 205/60/16 (5.2.3 (d) (i	i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing 205/60/16 (5.2.3 (d) (ii))	

МОТ #4	2018-11-26 11:13
MOT test number	748662602834
Result	🗸 Passed
Advice Rear Tyre worn close to legal limit/worn on edge both rear 3mm 205/60/16 ((5.2.3 (e))

МОТ #3	2017-11-10 10:46
MOT test number	810301870581
Result	✓ Passed
MOT #2	2016-11-09 11:09
MOT test number	796714377946
Result	✓ Passed
MOT #1	2015-12-09 17:17

MOT test number	935674097646
Result	✓ Passed



Tax & MOT check

✓	✓
Taxed	MOT
Tax due:	Expires:
1 March 2025	25 February 2025
Tax status	Valid until 1 March
Days left	307
MOT expiry date	25 February 2025
Full MOT history	<u>See MOT history</u>

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-06-18
Last registration	2024-02-26
Complete history	See info



Registration #1	2013-06-18	12 mi
Registration #2	2015-12-09	14.665 mi
Registration #3	2016-11-09	21.190 mi
Registration #4	2017-11-10	29.323 mi
Registration #5	2018-11-26	37.486 mi
Registration #6	2019-11-20	45.654 mi
Registration #7	2020-11-25	49.514 mi
Registration #8		11.777 esi
Registration #9		
Registration #10		11.227 est
Registration #10 Registration #11		11.117 est 11.117 est
-		0.000 es
Registration #11		0.000 est 0.000 est 0.000 est 0.000 est

More info \rightarrow



SG130NH report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1789 mm
Height	1561 mm
Length	4097 mm
Kerb weight	1335 kg
Max. allowed weight	1845 kg

Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	5	
Number of axles	2	
Engine number Carcheck.co.uk	72718693	page 12/12