




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	JETTA SPORT TDI
Colour	Silver
Year of manufacture	2009
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	7.1 mpg
Consumption combined	5.5 mpg
CO2 emission	143 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-21
Pictures	10
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-09
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	48
Total items failed	6

MOT #16	2024-01-10 09:27
MOT test number	708725683987
Result	✓ Passed
Next expiry date	2025-01-09
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on limit bald on edges (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2022-07-19 14:18
MOT test number	570344633807
Result	✓ Passed
Advice	N/s/f cvj boot small split

MOT #14	2022-07-19 08:14
MOT test number	894708839950
Result	✗ Failed
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	N/s/f cvj boot small split

**MOT #13**

2021-01-21 16:08

**MOT test number**

358312742418

**Result**

✓ Passed

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement bottom arm bush (5.3.4 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement console bush (5.3.4 (a) (i))

**MOT #12**

2021-01-20 09:35

**MOT test number**

143512925408

**Result**

✗ Failed

**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement bottom arm bush (5.3.4 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement console bush (5.3.4 (a) (i))

**MOT #11**

2020-11-18 13:17

**MOT test number**

535086825796

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement console bush (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement console bush (5.3.4 (a) (i))

**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2020-11-17 16:16

**MOT test number**

830004745973

**Result****✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement console bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement console bush (5.3.4 (a) (i))

**MOT #9**

2019-05-20 13:45

**MOT test number**

331461494603

**Result****✓ Passed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8**

2018-05-21 14:28

**MOT test number**

141873800770

**Result**

✓ Passed

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement console bush (5.3.4 (a) (i))

**Advice**

Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement console bush (5.3.4 (a) (i))

**MOT #7**

2017-05-16 15:12

**MOT test number**

209051455360

**Result**

✓ Passed

**Advice**

Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)

**Advice**

Nearside Rear Tyre worn close to the legal limit 2.5mm (4.1.E.1)

**Advice**

Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)

**Advice**

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #6**

2016-05-12 08:22

**MOT test number**

301567619071

**Result**

✓ Passed

**Advice**

Nearside Rear Tyre worn close to the legal limit 1.6mm (4.1.E.1)

**Advice**

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #5** 2015-05-14 13:53**MOT test number** 106324335164**Result** ✓ Passed**Notice** Wipers smearing slightly**Notice** Offside rear tyre has sawtooth wear on inner edge**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Nearside rear tyre has sawtooth wear on inner edge**MOT #4** 2015-05-14 12:04**MOT test number** 538264935160**Result** ✗ Failed**Fail** Front registration plate deteriorated (6.3.1d)**Notice** Offside rear tyre has sawtooth wear on inner edge**Notice** Nearside rear tyre has sawtooth wear on inner edge**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Wipers smearing slightly**MOT #3** 2014-05-15 10:22**MOT test number** 797605734141**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #2** 2013-05-21 10:34**MOT test number** 319661643179**Result** ✓ Passed



MOT #1	2012-05-10 09:02
MOT test number	855571632145
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Items removed from driver's view prior to test
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)





Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
9 January 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	9 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>ML09GXH</b>
Plate since	2024-03-28
Current registration	<b>ML09GXH</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-05-29
Last registration	2024-01-10
Complete history	<a href="#">See info</a>



Registration #1	2009-05-29	19 mi
Registration #2	2012-05-10	15.729 mi
Registration #3	2013-05-21	20.190 mi
Registration #4	2014-05-15	25.111 mi
Registration #5	2015-05-14	28.548 mi
Registration #6	2015-05-14	28.548 mi
Registration #7	2016-05-12	31.908 mi
Registration #8	2017-05-16	35.434 mi
Registration #9	2018-05-21	38.568 mi
Registration #10	2019-05-29	41.702 mi
Registration #11	2020-05-29	44.836 mi
Registration #12	2021-05-29	47.970 mi
Registration #13	2022-05-29	51.104 mi
Registration #14	2023-05-29	54.238 mi
Registration #15	2024-01-10	57.372 mi
Registration #16	2024-01-10	57.372 mi
Registration #17	2024-01-10	57.372 mi
Registration #18	2024-01-10	57.372 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1781 mm
Height	1459 mm
Length	4554 mm
Wheel base	2578 mm
Kerb weight	1411 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBD 013528