



report date: 2024-03-29

General information

Make	NISSAN
Model	NV200 DCI SE
Colour	White
Year of manufacture	2010
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 2.000 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-30
Pictures	1
Listing price	View report

AA

This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

aacars.com

source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-06
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	29
Total items failed	0

MOT #15	2023-10-07 09:05
MOT test number	537991931096
Result	✓ Passed
Next expiry date	2024-10-06

MOT #14	2022-10-03 16:13
MOT test number	488964466140
Result	✓ Passed

- Advice Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice Brake pedal wearing smooth (1.1.2 (c))
- Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #13**

2022-09-28 14:12

MOT test number

928650360463

Result**✗ Failed**

- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Offside Front Headlamp insecure (4.1.1 (c))
- MAJOR** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit 1.57 (8.2.2.2 (a))

MOT #12

2021-09-29 12:13

MOT test number

969714142878

Result**✓ Passed**

**MOT #11** 2021-09-29 11:02**MOT test number** 630848629493**Result** ✗ Failed**MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #10** 2021-03-30 14:52**MOT test number** 336969411523**Result** ✓ Passed**MOT #9** 2021-03-29 14:51**MOT test number** 994697266963**Result** ✗ Failed**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #8** 2020-04-03 13:11**MOT test number** 518182427936**Result** ✓ Passed**MOT #7** 2019-03-14 12:02**MOT test number** 568092893194**Result** ✓ Passed**MOT #6** 2018-03-09 10:46**MOT test number** 870126279512**Result** ✓ Passed

**MOT #5** 2017-02-28 14:57**MOT test number** 721625982303**Result** ✓ Passed**MOT #4** 2016-03-03 15:37**MOT test number** 111054247188**Result** ✓ Passed**MOT #3** 2015-03-03 15:39**MOT test number** 747202665070**Result** ✓ Passed**MOT #2** 2014-03-11 11:36**MOT test number** 238220474091**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Oil leak**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1** 2013-03-05 16:21**MOT test number** 475654463088**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
6 October 2024

Tax status	Valid until 1 October
-------------------	-----------------------

Days left	155
------------------	-----

MOT expiry date	6 October 2024
------------------------	----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	AK60VXE
Plate since	2019-09-29
Current registration	AK60VXE
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-10-29
Last registration	2023-10-07
Complete history	See info



Registration #1	2010-10-29	20 mi
Registration #2	2013-03-05	21.724 mi
Registration #3	2014-03-11	31.012 mi
Registration #4	2015-03-03	37.094 mi
Registration #5	2016-03-03	42.217 mi
Registration #6	2017-02-28	47.396 mi
Registration #7	2018-03-09	53.831 mi
Registration #8	2019-03-14	59.874 mi
Registration #9	2020-04-03	69.595 mi
Registration #10	2021-04-03	75.377 mi
Registration #11	2022-04-03	81.159 mi
Registration #12	2023-04-03	86.941 mi
Registration #13	2024-04-03	92.723 mi
Registration #14	2025-04-03	98.505 mi
Registration #15	2026-04-03	104.287 mi
Registration #16	2027-04-03	110.069 mi
Registration #17	2028-04-03	115.851 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1860 mm
Length	4400 mm
Kerb weight	1269 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Number of axles	2

Engine number

07188D