





report date: 2024-03-28

### General information

Make	NISSAN
Model	NAVARA DCI OUTLAW 4X4 SHR DCB
Colour	Blue
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	9.3 seconds
Gearbox	7 speed automatic

### Engine & fuel consumption

Power	231 BHP
Max. torque	550 Nm at 1.750 rpm
Engine capacity	2.991 cc
Cylinders	6
Fuel type	Diesel
Consumption city	22.2 mpg
Consumption extra urban	37.2 mpg
Consumption combined	29.7 mpg
CO2 emission	250 g/km
CO2 label	L



CarCheck.co.uk page 1/14



## Internet history

#### Entry 1

Date	2021-02-03	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/14



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-21
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	19
Total items failed	19

MOT #14	2024-01-22 15:11
MOT test number	398286023443
Result	✓ Passed
Next expiry date	2025-01-21

MOT #13	2023-03-14 15:34
MOT test number	927444949383
Result	<b>✓</b> Passed
Minor Headlamp cleaning device inoperative (4.1.6 (a) (i))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/14



**MOT #12** 2023-03-01 10:39

**MOT test number** 364143582958

**Result** X Failed

Fail Fluid leaking continuously posing a serious risk to road safety fuel filter inline (8.4.1 (a) (ii))

Fail Nearside Rear Direction indicator not working (4.4.1 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**Minor** Headlamp cleaning device inoperative (4.1.6 (a) (i))

Fail Windscreen washer not working (3.5 (a))

Fail Nearside Front Anti-roll bar linkage likely to become detached (5.3.3 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11** 2022-12-07 11:28

**MOT test number** 353322066297

Result × Failed

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/14



Result

EJ62XDY report date: 2024-03-28

× Failed

**MOT #10** 2019-08-21 15:52

MOT test number 645360761644

**Result** ✓ Passed

**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge Worn to 3mm (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Worn to 3mm (5.2.3 (e))

MOT #9 2019-08-20 08:28

**MOT test number** 848169755472

**Fail** Stop lamp(s) not working High Level (4.3.1 (a) (ii))

**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail** Nearside Headlamp aim too low (4.1.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge Worn to 3mm (5.2.3 (e))

**Fail** Offside Side repeater light intensity significantly reduced (4.4.3 (a))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Worn to 3mm (5.2.3 (e))

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #8 2018-08-29 13:28

**MOT test number** 418124768843

Result / Passed

CarCheck.co.uk page 5/14



MOT #7

MOT test number

790841303773

Result

Fail Offside Front Side repeater not working (4.4.1 (a) (ii))

MOT #6 2017-12-11 18:55 **MOT test number** 687757375856 Result ✓ Passed **MOT #5** 2017-12-11 18:55 **MOT** test number 153114892406 Result × Failed Pass with rectification Nearside Rear Registration plate lamp not working (1.1.C.1d) **Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)

 MOT #4
 2017-07-18 15:54

 MOT test number
 156891784993

 Result
 ✓ Passed

MOT #3

MOT test number

741881040203

Result

Advice Oil leak

2017-02-03 12:45

741881040203

CarCheck.co.uk page 6/14



MOT test number

Result

Advice Oil leak

Pass with rectification

Nearside Stop lamp not working (1.2.1b)

Nearside Stop lamp not working (1.2.1b)

 MOT #1
 2016-01-20 16:38

 MOT test number
 674389059151

 Result
 ✓ Passed

CarCheck.co.uk page 7/14



## Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	21 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 8/14



### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



## Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	IIK III
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-02-07
Last registration	2024-01-22
Complete history	See info



Registration #1	2013-02-07	21 mi
Registration #2	2016-01-20	53.372 mi
Registration #3	2017-02-03	72.227 mi
Registration #4	2017-02-03	72.227 mi
Registration #5	2017-07-18	72.852 mi
Registration #6	2017-12-11	74.945 mi
Registration #7	2017-12-11	74.945 mi
Registration #8	2018-08-29	79.331 mi
Posistration #0		
Registration #9		
Registration #10		0.074
		11.777 es
Registration #10		11.777 es
Registration #10 Registration #11		11.777 es 11.777 es 11.777 es
Registration #10 Registration #11 Registration #12		11.777 es 11.777 es 11.777 es 11.777 es
Registration #10 Registration #11 Registration #12 Registration #13		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 13/14



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1848 mm
Height	1795 mm
Length	5222 mm
Kerb weight	2150 kg
Max. allowed weight	3240 kg

# Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	23074C

CarCheck.co.uk page 14/14