





report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER S
Colour	Silver
Year of manufacture	2013
Top speed	141 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	190 BHP
Max. torque	260 Nm at 1.700 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date	2022-02-08
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

y -		
Date	2021-09-26	
Pictures	12	
Listing price	View report	









source: cargurus.co.uk

CarCheck.co.uk page 2/12



HF63RNU report date: 2024-03-28

MOT history

MOT expiry date	2025-03-17
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	12
Total items failed	0

MOT #10	2024-03-18 11:14
MOT test number	307053917825
Result	✓ Passed
Next expiry date	2025-03-17
Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Nearside Front Inner Suspension arm pin or bush worn but not re (5.3.4 (a) (i))	esulting in excessive movement

MOT #9	2024-03-13 16:0
MOT test	number 30203167701
Result	× Faile
MAJOR	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice (5.3.4 (a)	Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice (5.3.4 (a)	Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (i))

MOT #8	2023-03-15 14:12
MOT test number	512412537118
Result	✓ Passed

CarCheck.co.uk page 3/12



Result

HF63RNU

report date: 2024-03-28

✓ Passed

MOT #7 2021-09-21 15:23

MOT test number 741972154150

Result ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view Chip (3.2 (a) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #6 2020-06-01 15:57

MOT test number 963125987916

Result ✓ Passed

MOT #5 2019-09-09 11:00

MOT test number 866986357291

Result \rightarrow Passed

MOT #4 2019-09-07 08:12

MOT test number 817503553823

Result X Failed

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #3 2018-09-27 08:13

MOT test number 470851027053

1,7003102,703

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2017-09-16 08:00

MOT test number 107920889064

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2016-09-16 15:56

MOT test number 883734786053

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	17 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-09-30
Last registration	2024-03-18
Complete history	See info



Registration #1	2013-09-30	13 mi
Registration #2	2016-09-16	21.603 mi
Registration #3	2017-09-16	29.026 mi
Registration #4	2018-09-27	36.096 mi
Registration #5	2019-09-07	42.558 mi
Registration #6	2019-09-09	42.558 mi
Registration #7	2020-06-01	45.270 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 46
Registration #13		10.000 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	2 page 12	2/12