



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | C30 SPORT |
| Colour | Grey |
| Year of manufacture | 2009 |
| Top speed | 115 mph |
| 0 - 60 mph | 11.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 99 BHP |
| Max. torque | 150 Nm at 4.000 rpm |
| Engine capacity | 1.596 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 30.4 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 167 g/km |
| CO2 label | H |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-05 |
| Pictures | 20 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-16 |
| MOT pass rate | 67 % |
| MOT passed | 12 |
| Failed MOT tests | 6 |
| Total advice items | 50 |
| Total items failed | 5 |

| | |
|---------|------------------|
| MOT #18 | 2023-11-17 13:06 |
|---------|------------------|

| | |
|-----------------|--------------|
| MOT test number | 568002662287 |
|-----------------|--------------|

| | |
|--------|----------|
| Result | ✓ Passed |
|--------|----------|

| | |
|------------------|------------|
| Next expiry date | 2024-11-16 |
|------------------|------------|

| | |
|--------|--|
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Front Oil leak, but not excessive (8.4.1 (a) (i)) |
| Advice | Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Offside Rear Direction indicator slightly discoloured (4.4.3 (a)) |
| Advice | Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e)) |

**MOT #17**

2023-11-11 12:07

MOT test number

978820631974

Result**✗ Failed**

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- MAJOR** Front Fuel system component leaking needs investigation (6.1.3 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16

2022-09-29 13:25

MOT test number

581729788216

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15** 2022-09-29 11:28**MOT test number** 981974099556**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Nail in tyre**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2021-10-04 10:59**MOT test number** 663181945591**Result** ✓ Passed**MOT #13** 2020-06-12 14:49**MOT test number** 209904514187**Result** ✓ Passed**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides rear mountings (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12**

2019-07-20 11:39

MOT test number

118341866093

Result

✓ Passed

Advice Offside front headlamp light output weak and dim and just legal**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides rear mountings (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11**

2018-07-20 15:17

MOT test number

830834911393

Result

✓ Passed

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides rear bush (5.3.4 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**MOT #10**

2018-07-20 10:00

MOT test number

581083400821

Result

✗ Failed

DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides rear bush (5.3.4 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #9** 2017-07-20 10:24**MOT test number** 759740227908**Result** ✓ Passed**MOT #8** 2016-07-21 09:30**MOT test number** 254016799739**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-07-21 09:30**MOT test number** 299314523417**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2015-07-17 17:10**MOT test number** 595918395127**Result** ✓ Passed**MOT #5** 2015-07-17 17:10**MOT test number** 585868995111**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2014-07-29 15:08**MOT test number** 267540414234**Result** ✓ Passed



| | |
|-----------------|------------------|
| MOT #3 | 2013-07-25 16:37 |
| MOT test number | 396236603273 |
| Result | ✓ Passed |

| | |
|--|------------------|
| MOT #2 | 2013-07-25 14:15 |
| MOT test number | 536716203283 |
| Result | ✗ Failed |
| <div><div>Advice</div> Offside Front Tyre worn close to the legal limit (4.1.E.1)</div> <div><div>Pass with rectification</div> Windscreen wiper does not clear the windscreen effectively (8.2.2)</div> <div><div>Advice</div> Nearside Front Tyre worn close to the legal limit (4.1.E.1)</div> <div><div>Advice</div> Offside Rear Tyre worn close to the legal limit (4.1.E.1)</div> <div><div>Fail</div> Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)</div> <div><div>Pass with rectification</div> Nearside Headlamp not working on dipped beam (1.7.5a)</div> | |

| | |
|-----------------|------------------|
| MOT #1 | 2012-03-05 11:50 |
| MOT test number | 416765462010 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
16 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 2 |
| MOT expiry date | 16 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | YD09VYO |
| Plate since | 2024-03-29 |
| Current registration | YD09VYO |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 19 |
| First mileage registration | 2009-03-03 |
| Last registration | 2023-11-17 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2009-03-03 | 10 mi |
| Registration #2 | 2012-03-05 | 38.531 mi |
| Registration #3 | 2013-07-25 | 46.508 mi |
| Registration #4 | 2013-07-25 | 46.508 mi |
| Registration #5 | 2014-07-29 | 54.153 mi |
| Registration #6 | 2015-07-17 | 61.408 mi |
| Registration #7 | 2016-07-21 | 67.110 mi |
| Registration #8 | 2016-07-21 | 67.110 mi |
| Registration #9 | 2017-07-20 | 74.948 mi |
| Registration #10 | 2018-07-20 | 83.292 mi |
| Registration #11 | 2019-07-20 | 91.636 mi |
| Registration #12 | 2020-07-20 | 99.980 mi |
| Registration #13 | 2021-07-20 | 108.324 mi |
| Registration #14 | 2022-07-20 | 116.668 mi |
| Registration #15 | 2023-07-20 | 125.012 mi |
| Registration #16 | 2024-07-20 | 133.356 mi |
| Registration #17 | 2025-07-20 | 141.700 mi |
| Registration #18 | 2026-07-20 | 150.044 mi |
| Registration #19 | 2027-07-20 | 158.388 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1782 mm |
| Height | 1447 mm |
| Length | 4266 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1277 kg |
| Max. allowed weight | 1700 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 4 |

| | |
|---------------|--------|
| Engine number | 156670 |
|---------------|--------|