





report date: 2024-03-29

### General information

Make	BMW
Model	Z4 Z4 SDRIVE20I M SPORT ROADSTER
Colour	Black
Year of manufacture	2012
Top speed	146 mph
0 - 60 mph	6.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	184 BHP
Max. torque	270 Nm at 4.500 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



DG62CXC report date: 2024-03-29

Internet history

Entry 1

Date 2021-05-23
Pictures 1

Listing price <u>View report</u>



source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-09-02
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	16
Total items failed	7

MOT #13	2023-08-24 08:57
MOT test number	874358407457
Result	✓ Passed
Next expiry date	2024-09-02

MOT #12		2022-08-15 14:28
MOT test	number	746318321548
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #11	2022-08-10 15:04
MOT test number	261171565677
Result	<b>X</b> Failed
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Side repeater not working (4.4.1 (a) (ii))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #10	2021-08-13 08:15
MOT test number	223253707380
Result	✓ Passed

CarCheck.co.uk page 3/13



**Advice** 

Advice

DG62CXC

report date: 2024-03-29

**MOT** #9 2020-08-05 11:46 592973937101 **MOT** test number ✓ Passed Result **MOT #8** 2019-08-21 09:39 **MOT** test number 423262543445 Result ✓ Passed Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice **Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Both front & nearside rear tyres badly stepped tread

MOT test number

592406866303

Result

Fail Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #6	2019-08-15 10:45
MOT test number	283747968167
Result	<b>★</b> Failed
Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Offside Rear Road wheel fractured (5.2.2 (a))	
Fail Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.	1.11 (c))
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))

MOT #5		2018-08-07 08:14
MOT test	number	646576864839
Result		<b>✓</b> Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2017-08-23 14:39
MOT test number	558264261373
Result	✓ Passed
MOT #3	2016-09-03 10:41
MOT test number	864971138218
Result	✓ Passed
MOT #2	2015-08-25 17:16
MOT test number	378097235293
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1

MOT test number

269037035221

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 6/13



report date: 2024-03-29

#### Tax & MOT check

Tax expired: 9 January 2024





Expires: 2 September 2024

Tax status	Expired at 9 January 2024
Days left	111 days too late
MOT expiry date	2 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



DG62CXC report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



DG62CXC report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK CONTRACTOR
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-09-01
Last registration	2023-08-24
Complete history	See info



Registration #1	2012-09-01	21 mi
Registration #2	2015-08-25	27.386 mi
Registration #3	2015-08-25	27.386 mi
Registration #4	2016-09-03	38.512 mi
Registration #5	2017-08-23	44.711 mi
Registration #6	2018-08-07	50.976 mi
Registration #7	2019-08-15	54.792 mi
Registration #8	2019-08-16	54.792 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1790 mm
Height	1291 mm
Length	4239 mm
Wheel base	2496 mm
Kerb weight	1395 kg
Max. allowed weight	1725 kg

### Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	2 page 13/13