





General information

Make	FIAT
Model	QUBO MULTIJET DYNAMIC DUALOGIC
Colour	Red
Year of manufacture	2010
Top speed	96 mph
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	75 BHP	0 < 101 A
Max. torque	190 Nm at 1.750 rpm	101 - 120
Engine capacity	1.248 сс	121 - 140
Cylinders	4	141 - 165
Fuel type	Diesel	166 - 185
Consumption city	49.6 mpg	186 - 225
Consumption extra urban	74.3 mpg	225+
Consumption combined	62.8 mpg	
CO2 emission	115 g/km	
CO2 label	С	





Internet history

Entry 1

Date

2022-07-30

9

Pictures

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-04
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	22
Total items failed	4

MOT #15	2023-09-22 15:11
MOT test number	950931161001
Result	✓ Passed
Next expiry date	2024-10-04

MOT #14	2023-09-20 11:12
MOT test number	170442758491
Result	🗙 Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Offside Front Coil spring corroded (5.3.1 (b) (i))	

MOT #13	2022-10-05 08:25
MOT test number	349913512995
Result	✓ Passed
MOT #12	2021-07-29 09:41

MOT test number	431140255746
Result	✓ Passed





MOT #11	2020-09	9-30 18:07
MOT test i	number 7644	93819548
Result		🗸 Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))	
Advice	Slight corrosion; Exhaust, Rear axle.	
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))	

MOT #10	2020-09-30 10:26
MOT test number	586158380172
Result	🗙 Failed
Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.	2.3 (e))
Advice Slight corrosion; Exhaust, Rear axle.	
Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

MOT #9	2019-09-25 12:56
MOT test number	544267555083
Result	✓ Passed
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #8		2018-10-03 15:48
MOT test n	umber	312877126508
Result		🗸 Passed
Advice	Smell of fuel under rear of car	
Advice on body un	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords der wheel arch (5.2.3 (d) (i))	signs of tyre rubbing
Advice (2.1.5 (a))	Nearside Front Power steering component has slight seepage from a compo	onent inner rack end





MOT #7	2018-10-03 15:22
MOT test number	474486757446
Result	🗙 Failed
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords on body under wheel arch (5.2.3 (d) (i))	signs of tyre rubbing
Advice Smell of fuel under rear of car	
Minor Power steering fluid level below minimum (2.1.5 (b) (i))	
Advice Nearside Front Power steering component has slight seepage from a component (2.1.5 (a))	nent inner rack end
FailOffside Rear Tyre has ply or cords exposed signs of tyre rubbing on body under(ii))	wheel arch (5.2.3 (d)

MOT #6	2017-08-26 11:48
MOT test	number 297199314265
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened nearside and offside (3.5.1i)
Advice	Front Tyre worn close to the legal limit nearside and offside and worn on inner edges (4.1.E.1)

MOT #5	2016-08-27 10:40
MOT test number	796441074769
Result	✓ Passed
MOT #4	2016-02-17 12:31
MOT test number	323775730052
Result	✓ Passed
MOT #3	2015-03-17 14:47

	2013-03-17 14.47
MOT test number	397986275040
Result	✓ Passed





MOT #2		2014-04-22 12:09
MOT test	number	339622014174
Result		✓ Passed
Notice	Converted for wheelchair. presented with drivers seat only fitted	
MOT #1		2013-07-02 12:17
MOT test	number	275143383453
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Passenger seat(s) missing at time of test	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Off side front seat fitted only, conversion done	



DV10DYH report date: 2024-03-28

Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 4 October 2024
Tax status	Valid until 1 December
Days left	216
MOT expiry date	4 October 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K K
Damage 2	AMPL
	F Store
Date	 1. F
Category	 ant
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-08-16
Last registration	2023-09-22
Complete history	<u>See info</u>



Registration #1	2010-08-16	29 mi
Registration #2	2013-07-02	4.828 mi
Registration #3	2014-04-22	6.129 mi
Registration #4	2015-03-17	6.463 mi
Registration #5	2016-02-17	6.790 mi
Registration #6	2016-08-27	7.250 mi
Registration #7	2017-08-26	16.144 mi
Registration #8	2018-10-03	20.934 mi
Registration #9	2018-10-03	20.934 mi
Registration #10		11.777 est
Registration #11		11.777 esi
Registration #12		11.777 est
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

Dimensions & weight

Width	1716 mm
Height	1721 mm
Length	3595 mm
Wheel base	2513 mm
Kerb weight	1180 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	3604945