



General information

| | |
|---------------------|----------------|
| Make | VOLKSWAGEN |
| Model | POLO S |
| Colour | Black |
| Year of manufacture | 2007 |
| Top speed | 104 mph |
| 0 - 60 mph | 13.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 79 BHP |
| Max. torque | 132 Nm at 3.800 rpm |
| Engine capacity | 1.390 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 29.4 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 39.8 mpg |
| CO2 emission | 165 g/km |
| CO2 label | G |



**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2022-10-10 |
| MOT pass rate | 80 % |
| MOT passed | 12 |
| Failed MOT tests | 3 |
| Total advice items | 15 |
| Total items failed | 5 |

| | |
|-------------------------|-------------------------------------------------------------------|
| MOT #15 | 2021-10-11 14:54 |
| MOT test number | 492387172906 |
| Result | ✓ Passed |
| Next expiry date | 2022-10-10 |
| Advice | Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |

| | |
|------------------------|-------------------------------------------------------------------|
| MOT #14 | 2021-10-11 13:38 |
| MOT test number | 211024689968 |
| Result | ✗ Failed |
| Advice | Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |
| Fail | Rear fog lamp not working (4.5.1 (a) (ii)) |

| | |
|------------------------|------------------|
| MOT #13 | 2020-10-01 14:16 |
| MOT test number | 725985827173 |
| Result | ✓ Passed |

| | |
|------------------------|-----------------------------------------------------------------------------|
| MOT #12 | 2019-10-10 10:46 |
| MOT test number | 747626215862 |
| Result | ✓ Passed |
| Advice | Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) |
| Advice | Nail in tyre |

**MOT #11** 2019-10-03 13:56**MOT test number** 415321574600**Result** ✗ Failed**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nail in tyre**Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))**MOT #10** 2018-10-11 16:54**MOT test number** 105364208182**Result** ✓ Passed**MOT #9** 2018-01-04 17:00**MOT test number** 239542995783**Result** ✓ Passed**MOT #8** 2018-01-04 10:25**MOT test number** 479652745159**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Suspension arm rubber bush deteriorated resulting in excessive movement both side (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2016-10-27 09:45**MOT test number** 939805759818**Result** ✓ Passed**Advice** O/S/F tyre is worn low (3mm).**Advice** Coolant leak around the waterpump area.**MOT #6** 2015-10-27 13:38**MOT test number** 245906952237**Result** ✓ Passed**Advice** Offside front tyre wearing low**Advice** Front wishbone bushes worn**Advice** Coolant leak**MOT #5** 2014-10-22 11:29**MOT test number** 475685194236**Result** ✓ Passed**MOT #4** 2013-10-30 11:19**MOT test number** 288673603308**Result** ✓ Passed**MOT #3** 2012-10-16 11:18**MOT test number** 776840592231**Result** ✓ Passed**MOT #2** 2011-10-26 10:57**MOT test number** 285689791267**Result** ✓ Passed**Notice** O/s front tyre wearing low



| | |
|---------------------------------------------|------------------|
| MOT #1 | 2010-10-26 12:04 |
| MOT test number | 324999990440 |
| Result | ✓ Passed |
| <div>NoticeO/s front tyre wearing low</div> | |



Tax & MOT check

✕
Untaxed

Tax expired:
13 May 2022

✕
MOT

Expired:
10 October 2022

| | |
|------------------|---------------------------------|
| Tax status | Expired at 13 May 2022 |
| Days left | 716 days too late |
| MOT expiry date | 10 October 2022 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|-----------------------------------------|------------|
| Vehicle class | 48 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2007-10-30 |
| Last registration | 2021-10-11 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-10-30 | 12 mi |
| Registration #2 | 2010-10-26 | 14.347 mi |
| Registration #3 | 2011-10-26 | 18.126 mi |
| Registration #4 | 2012-10-16 | 20.983 mi |
| Registration #5 | 2013-10-30 | 23.755 mi |
| Registration #6 | 2014-10-22 | 25.905 mi |
| Registration #7 | 2015-10-27 | 27.592 mi |
| Registration #8 | 2016-10-27 | 28.645 mi |
| Registration #9 | 2016-10-27 | 28.645 mi |
| Registration #10 | 2016-10-27 | 28.645 mi |
| Registration #11 | 2016-10-27 | 28.645 mi |
| Registration #12 | 2016-10-27 | 28.645 mi |
| Registration #13 | 2016-10-27 | 28.645 mi |
| Registration #14 | 2016-10-27 | 28.645 mi |
| Registration #15 | 2016-10-27 | 28.645 mi |
| Registration #16 | 2016-10-27 | 28.645 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1759 mm |
| Height | 1479 mm |
| Length | 4204 mm |
| Wheel base | 2578 mm |
| Kerb weight | 1142 kg |
| Max. allowed weight | 1770 kg |

Additional information

| | |
|-----------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | BUD 077170 |