



report date: 2024-03-29

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Silver
Year of manufacture	2013
Top speed	96 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 2

Date	2021-07-17
Pictures	10
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-02
Pictures	10
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-15
MOT pass rate	50 %
MOT passed	8
Failed MOT tests	8
Total advice items	16
Total items failed	15

MOT #16	2023-09-15 15:29
MOT test number	204285231290
Result	✓ Passed
Next expiry date	2024-09-15
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #15	2023-09-15 08:32
MOT test number	638570446005
Result	✗ Failed
Fail	Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #14	2022-09-16 09:39
MOT test number	456287089108
Result	✓ Passed

MOT #13	2022-09-16 09:39
MOT test number	226843769081
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #12** 2021-11-13 11:22**MOT test number** 739562239273**Result** ✓ Passed**MOT #11** 2021-11-13 11:22**MOT test number** 462763670979**Result** ✗ Failed**Pass with rectification** Front Horn not working fuse fitted (7.7 (a))**MOT #10** 2020-11-24 18:48**MOT test number** 793051495614**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2020-11-24 18:48**MOT test number** 365475418836**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-05-22 17:52**MOT test number** 499487882708**Result** ✓ Passed

**MOT #7** 2019-05-01 09:02**MOT test number** 711699751712**Result** ✗ Failed**Fail** Front Brake disc significantly and obviously worn both side (1.1.14 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #6** 2018-03-21 13:53**MOT test number** 491984837281**Result** ✓ Passed**Advice** Offside Front Wing mirror has damage on rear cover**MOT #5** 2018-03-21 13:53**MOT test number** 223179045289**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Offside Front Wing mirror has damage on rear cover**Pass with rectification** Offside Front Headlamp aim too high (1.8)**MOT #4** 2017-03-15 14:11**MOT test number** 341874445240**Result** ✓ Passed



MOT #3	2017-03-15 14:11
MOT test number	481254472386
Result	✗ Failed
Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)

MOT #2	2016-03-16 14:05
MOT test number	375167432455
Result	✓ Passed
Advice	Child seat base fitted.
Advice	O/s/f lower arm rear bush perished.
Advice	N/s/f lower arm rear bush separated.

MOT #1	2016-03-16 12:37
MOT test number	212696956853
Result	✗ Failed
Advice	O/s/f lower arm rear bush perished.
Fail	Nearside Stop lamp not working (1.2.1b)
Advice	N/s/f lower arm rear bush separated.
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	O/s wiper slightly smearing.
Advice	Child seat base fitted.



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✓
MOT

Expires:
15 September 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	15 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2013-03-21
Last registration	2023-09-15
Complete history	See info



Registration #1	2013-03-21	24 mi
Registration #2	2016-03-16	39.133 mi
Registration #3	2016-03-16	39.133 mi
Registration #4	2017-03-15	53.271 mi
Registration #5	2017-03-15	53.271 mi
Registration #6	2018-03-21	69.591 mi
Registration #7	2018-03-21	69.591 mi
Registration #8	2019-05-01	88.373 mi
Registration #9	2019-05-22	88.382 mi
Registration #10	2020-11-24	93.105 mi
Registration #11	2020-11-24	93.105 mi
Registration #12	2020-11-24	93.105 mi
Registration #13	2020-11-24	93.105 mi
Registration #14	2020-11-24	93.105 mi
Registration #15	2020-11-24	93.105 mi
Registration #16	2020-11-24	93.105 mi
Registration #17	2020-11-24	93.105 mi
Registration #18	2020-11-24	93.105 mi
Registration #19	2020-11-24	93.105 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	153324