




General information

Make	MINI
Model	MINI (R60) ONE
Colour	Black
Year of manufacture	2011
Top speed	107 mph
0 - 60 mph	11.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 3.000 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2022-01-22
Pictures	56
Listing price	<a href="#">View report</a>



**AA** This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

aacars.com



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-05
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	38
Total items failed	2

MOT #13 2024-03-06 10:37

MOT test number 727665772582

Result ✓ Passed

Next expiry date 2025-03-05

- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))



<b>MOT #12</b>	2024-03-06 10:37
<b>MOT test number</b>	231439664752
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Rear Child Seat fitted not allowing full inspection of adult belt
<b>Pass with rectification</b>	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
<b>Advice</b>	Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Items removed from driver's view prior to test
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #11</b>	2023-02-23 16:30
<b>MOT test number</b>	757526762768
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Nail in tyre
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

<b>MOT #10</b>	2023-02-23 11:36
<b>MOT test number</b>	277429589065
<b>Result</b>	✗ Failed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Nearside Rear Nail in tyre
<b>Fail</b>	Front Windscreen washer not working (3.5 (a))



MOT #9 2022-02-24 16:48

MOT test number 954278980006

Result ✓ Passed

MOT #8 2021-08-31 11:50

MOT test number 290712987760

Result ✓ Passed

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Coolant leak

**Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Brake wear light on

MOT #7 2020-08-28 09:39

MOT test number 786386671778

Result ✓ Passed

**Advice** Rear Child Seat fitted not allowing full inspection of adult belt Nearside and offside

**Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))

**Advice** Light corrosion to front and rear sub frames

**Advice** Items removed from driver's view prior to test From mirror

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Front Vehicles internal headlight adjuster altered to recheck lights

**Advice** Rear Inner Brake pad(s) wearing thin Nearside and offside (1.1.13 (a) (ii))

MOT #6 2019-08-09 15:03

MOT test number 642581169664

Result ✓ Passed

**Advice** Tyre worn close to legal limit/worn on edge Both fronts badly worn on edges (5.2.3 (e))



<b>MOT #5</b>	2018-08-30 09:28
<b>MOT test number</b>	875003806315
<b>Result</b>	✓ Passed
<b>Advice</b>	Child Seat fitted not allowing full inspection of adult belt Rears

<b>MOT #4</b>	2017-08-17 09:11
<b>MOT test number</b>	844613596358
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

<b>MOT #3</b>	2016-08-24 10:27
<b>MOT test number</b>	768657331622
<b>Result</b>	✓ Passed

<b>MOT #2</b>	2015-09-03 00:00
<b>MOT test number</b>	849890460055
<b>Result</b>	✓ Passed
<b>Advice</b>	Child seat fitted to rear,seatbelt not fully tested

<b>MOT #1</b>	2014-09-03 15:25
<b>MOT test number</b>	435976244293
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 February 2025

✓  
**MOT**

**Expires:**  
5 March 2025

**Tax status** Valid until 1 February

**Days left** 278

**MOT expiry date** 5 March 2025

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>YX11</b>
Plate since	2019-09-29
Current registration	<b>YX11</b>
Plate since	2019-09-29

More info >



**Finance check**

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	15
<b>First mileage registration</b>	2011-09-02
<b>Last registration</b>	2024-03-06
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2011-09-02	27 mi
<b>Registration #2</b>	2014-09-03	17.281 mi
<b>Registration #3</b>	2015-09-03	28.336 mi
<b>Registration #4</b>	2016-08-24	38.810 mi
<b>Registration #5</b>	2017-08-17	53.020 mi
<b>Registration #6</b>	2018-08-30	65.906 mi
<b>Registration #7</b>	2019-08-09	76.885 mi
<b>Registration #8</b>	2020-08-28	84.109 mi
<b>Registration #9</b>	2021-08-09	91.333 mi
<b>Registration #10</b>	2022-08-09	98.557 mi
<b>Registration #11</b>	2023-08-09	105.781 mi
<b>Registration #12</b>	2024-03-06	113.005 mi
<b>Registration #13</b>	2024-03-06	120.229 mi
<b>Registration #14</b>	2024-03-06	127.453 mi
<b>Registration #15</b>	2024-03-06	134.677 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1265 kg
Max. allowed weight	1735 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

A767J014