



General information

Make	MINI
Model	UNKNOWN COOPER
Colour	Silver
Year of manufacture	2015
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 4.300 rpm
Engine capacity	1.499 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	123 g/km
CO2 label	D





Internet history

Entry 2


Date	2022-07-05
Pictures	46
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-10-24
Pictures	20
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-08-17
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	11
Total items failed	0

MOT #6	2023-08-04 08:36
MOT test number	271986039030
Result	✓ Passed
Next expiry date	2024-08-17

MOT #5	2022-08-18 10:03
MOT test number	589569891286
Result	✓ Passed

MOT #4	2021-10-15 09:26
MOT test number	257345808167
Result	✓ Passed

**Minor** Windscreen damaged but not adversely affecting driver's view chip in screen (3.2 (a) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge tyre is down to 2mm, and has very heavy inner edge wear, advise alignment check on rear (5.2.3 (e))

**Minor** Front Windscreen wiper blade defective wipers are streaky (3.4 (b) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge tyre at 3mm, and has a nail in tread (5.2.3 (e))

**MOT #3** 2020-10-27 12:14**MOT test number** 358385869674**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2019-10-30 13:35**MOT test number** 609298577625**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge heavy edge wear (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view large chip in screen outside of 'a' zone but less than 40mm (3.2 (a) (i))**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Tyre slightly damaged/cracking or perishing rubber cracking in tread area/tread grooves (5.2.3 (d) (ii))**Advice** Tpms lamp on**MOT #1** 2018-10-09 15:14**MOT test number** 774932743420**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
17 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	17 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>FP65NHH</b>
Plate since	2019-09-28
Current registration	<b>FP65NHH</b>
Plate since	2019-09-28

More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-10-31
Last registration	2023-08-04
Complete history	<a href="#">See info</a>



Registration #1	2015-10-31	23 mi
Registration #2	2018-10-09	20.120 mi
Registration #3	2019-10-30	27.168 mi
Registration #4	2020-10-27	31.347 mi
Registration #5	2021-10-15	34.427 mi
Registration #6	2022-10-20	35.377 mi
Registration #7	2022-10-20	35.377 mi
Registration #8	2022-10-20	35.377 mi
Registration #9	2023-08-04	35.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2022 mm
Height	1441 mm
Length	4253 mm
Wheel base	2670 mm
Kerb weight	1395 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Engine number**

F9971242