



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO GBT
Colour	White
Year of manufacture	2012
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E






Internet history

Entry 2

Date	2022-01-11
Pictures	16
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2022-01-03
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-07-20
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	36
Total items failed	3

MOT #14	2023-07-21 12:07
MOT test number	213880704081
Result	✓ Passed
Next expiry date	2024-07-20
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13	2023-07-21 12:07
MOT test number	178416592496
Result	✗ Failed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12	2022-06-28 15:07
MOT test number	595168640105
Result	✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Central Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #11**

2022-06-28 15:07

**MOT test number**

710942808780

**Result****✗ Failed****Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Central Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #10**

2021-08-25 13:29

**MOT test number**

561637146247

**Result****✓ Passed****Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened pitted inner surface (1.1.14 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Direction indicator slightly discoloured in bumper (4.4.3 (a))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front pipe flex is in poor condition**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened pitted inner surface (1.1.14 (a) (ii))**Advice** Nearside Front Direction indicator slightly discoloured in bumper (4.4.3 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Osf inner arch plastic is showing signs of the tyre touching but not making contact time of test/the nsf inner arch plastic is missing**Advice** Oil leak, but not excessive nsf gearbox oil sill area (8.4.1 (a) (i))

**MOT #9** 2021-08-20 10:46**MOT test number** 642360884757**Result** ✗ Failed**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2020-08-12 09:32**MOT test number** 274087983525**Result** ✓ Passed**Advice** Rear exhaust box starting to deteriorated**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #7** 2019-08-30 13:59**MOT test number** 292227087186**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge and worn on edges (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge and worn on edges (5.2.3 (e))**MOT #6** 2018-11-26 17:01**MOT test number** 605739885171**Result** ✓ Passed**MOT #5** 2018-11-26 09:39**MOT test number** 830102344746**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #4** 2017-11-29 16:08**MOT test number** 619230703126**Result** ✓ Passed**MOT #3** 2016-09-29 08:31**MOT test number** 779905288515**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit 2.5mm 185/65/15 88t worn on outer edge (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit 2mm 185/65/15 88t worn on outer edge (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit 2.5mm 185/65/15 88t (4.1.E.1)

**MOT #2** 2016-09-21 11:31**MOT test number** 618342304146**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit 2.5mm 185/65/15 88t worn on outer edge (4.1.E.1)
- Fail** Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.A.3)
- Advice** Nearside Front Tyre worn close to the legal limit 2mm 185/65/15 88t worn on outer edge (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit 2.5mm 185/65/15 88t (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #1** 2015-09-23 10:15**MOT test number** 232823602244**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
20 July 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	20 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-09-29
Last registration	2023-07-21
Complete history	<a href="#">See info</a>



Registration #1	2012-09-29	17 mi
Registration #2	2015-09-23	18.657 mi
Registration #3	2016-09-21	30.355 mi
Registration #4	2016-09-29	30.570 mi
Registration #5	2017-11-29	42.525 mi
Registration #6	2018-11-26	49.635 mi
Registration #7	2018-11-26	49.635 mi
Registration #8	2019-08-30	55.447 mi
Registration #9	2020-08-12	60.978 mi
Registration #10	2020-08-12	60.978 mi
Registration #11	2020-08-12	60.978 mi
Registration #12	2020-08-12	60.978 mi
Registration #13	2020-08-12	60.978 mi
Registration #14	2020-08-12	60.978 mi
Registration #15	2020-08-12	60.978 mi
Registration #16	2020-08-12	60.978 mi
Registration #17	2020-08-12	60.978 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	0029360