



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Blue
Year of manufacture	2006
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	129 Nm at 4.400 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-09
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-16
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	35
Total items failed	7

MOT #19	2023-08-14 08:00
MOT test number	460460827762
Result	✓ Passed
Next expiry date	2024-08-16
Advice	Car rusty underside

MOT #18	2022-08-17 08:51
MOT test number	918976518554
Result	✓ Passed
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Several areas of corrosion to front strutt towers, front and rear suspension componants including rear shock absorber bodies. Not yet reached fail criteria
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #17** 2021-08-16 10:32**MOT test number** 702637929014**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Perishing (dot 5012) (5.2.3 (d) (ii))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Perishing (dot 5112) (5.2.3 (d) (ii))**Advice** Offside Front Slight brake bind on hand rotation.**MOT #16** 2020-08-10 11:26**MOT test number** 464836928264**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Edges worn. (5.2.3 (e))**MOT #15** 2020-08-06 14:25**MOT test number** 795197860754**Result** ✗ Failed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Corroded. (1.1.11 (c))**Fail** Offside Rear Upper Suspension component attachment bracket/mounting corroded and seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Edges worn. (5.2.3 (e))**Advice** Nearside Rear Upper Top suspension mount heavily corroded.**Advice** Offside Rear Brake pipe corroded, covered in grease or other material Corroded. (1.1.11 (c))

**MOT #14**

2019-04-23 11:50

MOT test number

421715742614

Result

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Integral body structure is corroded but structural rigidity is not significantly reduced Inner sill corroded (6.1.1 (c) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))
- Advice** Nearside Rear Integral body structure is corroded but structural rigidity is not significantly reduced Inner sill corroded (6.1.1 (c) (i))

MOT #13

2019-04-23 08:59

MOT test number

982856932156

Result

✗ Failed

- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Electronic power steering warning lamp indicates a system malfunction (2.6 (a))
- Advice** Offside Rear Integral body structure is corroded but structural rigidity is not significantly reduced Inner sill corroded (6.1.1 (c) (i))
- Advice** Front Brake disc worn, but not excessively Both front (1.1.14 (a) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Integral body structure is corroded but structural rigidity is not significantly reduced Inner sill corroded (6.1.1 (c) (i))
- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))

**MOT #12** 2018-04-16 09:22**MOT test number** 643196741168**Result** ✓ Passed**Advice** Front brake fluctuating, but not excessively (3.7.B.3)**Advice** Offside Front Brake hose has slight corrosion to ferrules At middle joint (3.6.B.4e)**Advice** Nearside Front Brake hose has slight corrosion to ferrules At middle joint (3.6.B.4e)**MOT #11** 2017-04-04 10:47**MOT test number** 190537633171**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)**Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)**MOT #10** 2016-04-22 08:28**MOT test number** 877341665874**Result** ✓ Passed**MOT #9** 2015-04-27 09:39**MOT test number** 785587715140**Result** ✓ Passed**MOT #8** 2015-04-27 09:39**MOT test number** 235537515442**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #7** 2014-04-01 10:17**MOT test number** 538321694016**Result** ✓ Passed**MOT #6** 2013-04-03 10:11**MOT test number** 488753193033**Result** ✓ Passed**Advice** Nearside Inner Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2013-04-03 10:11**MOT test number** 465683793070**Result** ✗ Failed**Pass with rectification** Centre Upper Stop lamp not working (1.2.1b)**Advice** Nearside Inner Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2012-04-13 09:56**MOT test number** 449974402117**Result** ✓ Passed**MOT #3** 2011-04-26 13:47**MOT test number** 558116511184**Result** ✓ Passed**MOT #2** 2010-04-23 16:06**MOT test number** 214743210439**Result** ✓ Passed**MOT #1** 2009-04-23 12:23**MOT test number** 973293319185**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
16 August 2024

Tax status		Valid until 1 October
Days left		154
MOT expiry date		16 August 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-04-26
Last registration	2023-08-14
Complete history	See info



Registration #1	2006-04-26	26 mi
Registration #2	2009-04-23	9.348 mi
Registration #3	2010-04-23	13.801 mi
Registration #4	2011-04-26	18.333 mi
Registration #5	2012-04-13	22.523 mi
Registration #6	2013-04-03	26.206 mi
Registration #7	2014-04-01	30.195 mi
Registration #8	2015-04-27	34.158 mi
Registration #9	2016-04-22	37.612 mi
Registration #10	2017-04-04	40.558 mi
Registration #11	2018-04-04	43.504 mi
Registration #12	2019-04-04	46.450 mi
Registration #13	2020-04-04	49.396 mi
Registration #14	2021-04-04	52.342 mi
Registration #15	2022-04-04	55.288 mi
Registration #16	2023-04-04	58.234 mi
Registration #17	2024-04-04	61.180 mi
Registration #18	2025-04-04	64.126 mi
Registration #19	2026-04-04	67.072 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4ZZU798028