






General information

Make	MINI
Model	MINI COOPER S
Colour	White
Year of manufacture	2013
Top speed	141 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	190 BHP
Max. torque	260 Nm at 1.700 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history	
Entry 1	
Date	2021-08-04
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-10
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	11
Total items failed	1

МОТ #9	2023-09-11 07:23
MOT test number	243082759808
Result	✓ Passed
Next expiry date	2024-09-10
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8	2022-09-08 10:01
MOT test number	494133094456
Result	✓ Passed

MOT #7	2021-08-13 10:52
MOT test number	973415465875
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))





МОТ #6		2021-08-13 10:52
MOT test number		796676764695
Result		🗙 Failed
Minor Nearside Rear Re (4.7.1 (b) (i))	gistration plate lamp inoperative in the case of	multiple lamps or light sources
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification	Offside Front Position lamp not working (4.2.1	(a) (ii))
Minor Front Windscreen	damaged but not adversely affecting driver's v	/iew (3.2 (a) (i))

MOT #5	2020-09-11 11:49
MOT test number	567883755789
Result	✓ Passed

МОТ #4	2018-10-03 11:39
MOT test number	804173442023
Result	✓ Passed

MOT #3	2018-10-02 10:13
MOT test number	376666173339
Result	🗙 Failed

MAJOR Oil leaking excessively from transmission (8.4.1 (a) (i))

MOT #2		2017-10-06 09:41
MOT test	number	867912788923
Result		✓ Passed
Advice	Offside Rear Advise rear right passenger door will not open from inside.	
Advice (6.3.1d)	Central Front registration plate faded but not likely to be misread Front numb	per plate faded
Advice	Nearside Rear Brake pad(s) wearing thin Rear left and right pads low 3mm (3	3.5.1g)





MOT #1	2016-10-07 13:49
MOT test number	202688319366
Result	✓ Passed



Tax & MOT check

Tax due:	✓ MOT Expires: 10 September 2024
1 August 2024 Tax status	Valid until 1 August
Days left	93
MOT expiry date	10 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-12-24
Last registration	2023-09-11
Complete history	<u>See info</u>



Registration #1	2013-12-24	29 mi
Registration #2	2016-10-07	31.340 mi
Registration #3	2017-10-06	44.050 mi
Registration #4	2018-10-02	57.452 mi
Registration #5	2018-10-03	57.452 mi
Registration #6	2020-09-11	80.104 mi
Registration #7		11.777 mi
Registration #8		11.777 mi
Registration #9		11.777 mi
Registration #10		11.777 mi
Registration #11		11.777 mi





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
50569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1892 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	2 page 12/12

Engine number

A079J479