



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA 16V MULTIJET CROSS
Colour	Green
Year of manufacture	2008
Top speed	93 mph
0 - 60 mph	18.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	145 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	67.3 mpg
Consumption combined	54.3 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-19
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-27
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	48
Total items failed	13

MOT #18	2023-11-13 14:08
MOT test number	203193673677
Result	✓ Passed
Next expiry date	2024-11-27
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #17	2022-11-28 14:50
MOT test number	770422820497
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Centre prop bearing/mount rubber (inside housing) badly wprn and deteriorated
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm 175/65/15 (5.2.3 (e))

**MOT #16**

2022-11-28 14:50

MOT test number

745524156676

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm 175/65/15 (5.2.3 (e))
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Centre prop bearing/mount rubber (inside housing) badly worn and deteriorated
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15

2022-07-19 10:06

MOT test number

232752572553

Result**✗ Failed**

- Advice** Centre prop bearing/mount rubber (inside bearing housing) badly worn and deteriorated
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm 175/65/15 (5.2.3 (e))
- Fail** Exhaust emissions exceed manufacturer's specified limit 1.29 (8.2.2.2 (a))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #14** 2021-06-14 09:49**MOT test number** 596785914123**Result** ✓ Passed**MOT #13** 2021-06-05 12:44**MOT test number** 974314605609**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #12** 2020-06-16 13:57**MOT test number** 499236653829**Result** ✓ Passed**MOT #11** 2020-06-13 10:02**MOT test number** 828572837004**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Rear Brake disc in such a condition that it is seriously weakened heavily corroded (1.1.14 (a) (ii))**Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (l))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

**MOT #10** 2019-06-25 09:53**MOT test number** 864326194854**Result** ✓ Passed**MOT #9** 2018-07-12 13:23**MOT test number** 361731082627**Result** ✓ Passed**Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))**MOT #8** 2017-07-27 11:40**MOT test number** 463627282985**Result** ✓ Passed**Advice** Nearside wiper blade split**Advice** Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)**MOT #7** 2016-05-27 15:38**MOT test number** 607308406051**Result** ✓ Passed**Advice** Nearside Rear Upper Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened Corrosion to surface of disc from being stood (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened Corrosion to surface of disc from being stood (3.5.1i)**Advice** Offside Front Upper Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened Corrosion to surface of disc from being stood (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened Corrosion to surface of disc from being stood (3.5.1i)

**MOT #6** 2015-01-28 12:54**MOT test number** 736718125057**Result** ✓ Passed

- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5 2014-01-27 09:36**MOT test number** 235427324055**Result** ✓ Passed**MOT #4** 2013-01-22 09:47**MOT test number** 328182623009**Result** ✓ Passed

- Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)

MOT #3 2012-01-30 16:20**MOT test number** 839230432051**Result** ✓ Passed**MOT #2** 2012-01-30 14:54**MOT test number** 186920432076**Result** ✗ Failed

- Fail** Nearside Rear Shock absorber has an excessively worn bush (2.7.4)
- Fail** Offside Front Headlamp aim too high (1.8)
- Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)
- Fail** Nearside Front Headlamp aim too high (1.8)



MOT #12011-07-26 10:55

MOT test number569877201247

Result

✓ Passed

- Notice

Offside rear brake disc slightly pitted
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice

Nearside rear brake disc slightly pitted



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
27 November 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	27 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-07-31
Last registration	2023-11-13
Complete history	See info



Registration #1	2008-07-31	22 mi
Registration #2	2011-07-26	11.448 mi
Registration #3	2012-01-30	13.386 mi
Registration #4	2012-01-30	13.386 mi
Registration #5	2013-01-22	16.932 mi
Registration #6	2014-01-27	22.668 mi
Registration #7	2015-01-28	30.893 mi
Registration #8	2016-05-27	40.017 mi
Registration #9	2017-07-27	47.631 mi
Registration #10	2018-07-12	49.147 mi
Registration #11	2019-01-22	51.277 mi
Registration #12	2019-01-22	51.277 mi
Registration #13	2019-01-22	51.277 mi
Registration #14	2019-01-22	51.277 mi
Registration #15	2019-01-22	51.277 mi
Registration #16	2019-01-22	51.277 mi
Registration #17	2019-01-22	51.277 mi
Registration #18	2019-01-22	51.277 mi
Registration #19	2019-01-22	51.277 mi
Registration #20	2019-01-22	51.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2305 mm
Kerb weight	1075 kg
Max. allowed weight	1535 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	2837597