



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO MATCH (60BHP)
Colour	Silver
Year of manufacture	2008
Top speed	97 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-23
Pictures	19
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-12
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	54
Total items failed	18

MOT #192023-06-13 15:14

MOT test number278232741350

Result✓ Passed

Next expiry date2024-06-12

- Advice**Oil leak, but not excessive Around sump area (8.4.1 (a) (i))
- Advice**Offside Rear Tail light lens cracked, no effecting light emitting
- Minor**Nearside Front Side repeater lens defective which has no effect on emitted light Wing mirror indicator (4.4.1 (b) (i))
- Advice**Front Brake disc worn, pitted or scored, but not seriously weakened OSF & NSF (1.1.14 (a) (ii))
- Advice**Front Service brake fluctuating, but not excessively OSF & NSF (1.2.1 (e))
- Advice**Nearside Rear Reg plate bulb insecure
- Advice**Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor**Nearside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #18**

2023-06-13 08:28

**MOT test number**

218451004191

**Result****✗ Failed****Advice** Offside Rear Tail light lens cracked, no effecting light emitting**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Nearside Front Upper Coil spring insecure (5.3.1 (a) (i))**Minor** Nearside Front Side repeater lens defective which has no effect on emitted light Wing mirror indicator (4.4.1 (b) (i))**Fail** Nearside Front Upper Macpherson strut pin or bush likely to become detached (5.3.4 (a) (ii))**Advice** Oil leak, but not excessive Around sump area (8.4.1 (a) (i))**Advice** Nearside Rear Reg plate bulb insecure**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Front Service brake fluctuating, but not excessively OSF & NSF (1.2.1 (e))**Minor** Nearside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened OSF & NSF (1.1.14 (a) (ii))

**MOT #17**

2023-05-30 10:28

**MOT test number**

168621703804

**Result**

✗ Failed

- Minor** Nearside Registration plate lamp insecure (4.7.1 (c) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both. Inner faces (1.1.14 (a) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Minor** Offside Rear Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #16**

2022-06-09 15:41

**MOT test number**

757308506348

**Result**

✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #15**

2022-05-30 12:01

**MOT test number**

624041708996

**Result****✗ Failed**

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #14**

2021-05-26 12:23

**MOT test number**

588987559486

**Result****✓ Passed**

**Advice** Exhaust deteriorated

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #13**

2021-05-20 08:51

**MOT test number**

834047137759

**Result****✗ Failed**

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Child Seat fitted not allowing full inspection of adult belt

**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

**Advice** Exhaust deteriorated

**MOT #12**

2020-05-29 13:15

**MOT test number**

974664636401

**Result**

✓ Passed

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice**

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11**

2019-06-07 13:07

**MOT test number**

522782748616

**Result**

✓ Passed

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Items removed from driver's view prior to test

**Advice**

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice**

Exhaust deteriorated

**MOT #10**

2019-06-04 13:00

**MOT test number**

146954918063

**Result**

✗ Failed

**Advice**

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail**

Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

**Advice**

Items removed from driver's view prior to test

**Fail**

Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**Advice**

Exhaust deteriorated

**Fail**

Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MOT #9** 2018-04-03 09:43**MOT test number** 381941080589**Result** ✓ Passed**MOT #8** 2017-05-22 11:09**MOT test number** 853248200491**Result** ✓ Passed**Advice** Items removed from driver's view prior to test AIR FRESHNER**Advice** OFFSIDE WASHER JET WEAK BUT STILL PROVIDES SUFFICIENT LIQUID**Advice** REAR EXHAUST SCILENCER OUTER SKIN DETERIOATING**MOT #7** 2017-05-20 10:13**MOT test number** 876648432901**Result** ✗ Failed**Advice** OFFSIDE WASHER JET WEAK BUT STILL PROVIDES SUFFICIENT LIQUID**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** REAR EXHAUST SCILENCER OUTER SKIN DETERIOATING**Advice** Items removed from driver's view prior to test AIR FRESHNER**Fail** Nearside Rear rear brake binding (3.7.B.1)**MOT #6** 2016-05-09 08:56**MOT test number** 969613856863**Result** ✓ Passed**Advice** Under trays and engine covers fitted obscuring some components





MOT #5	2015-03-21 10:38
MOT test number	128230585493
Result	✓ Passed
<div>Notice Front tyres cracking</div>	
MOT #4	2014-03-28 12:11
MOT test number	149787484088
Result	✓ Passed
MOT #3	2013-03-22 09:59
MOT test number	747331983096
Result	✓ Passed
MOT #2	2012-03-07 16:43
MOT test number	836817662038
Result	✓ Passed
MOT #1	2011-03-03 16:05
MOT test number	696692561026
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
12 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	12 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>YY08AEZ</b>
Plate since	2019-09-29
Current registration	 <b>YY08AEZ</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-26
Last registration	2023-06-13
Complete history	<a href="#">See info</a>



Registration #1	2008-03-26	16 mi
Registration #2	2011-03-03	17.012 mi
Registration #3	2012-03-07	22.277 mi
Registration #4	2013-03-22	28.673 mi
Registration #5	2014-03-28	34.411 mi
Registration #6	2015-03-21	41.670 mi
Registration #7	2016-05-09	54.216 mi
Registration #8	2017-05-20	64.900 mi
Registration #9	2017-05-22	64.901 mi
Registration #10	2018-04-03	69.282 mi
Registration #11	2019-06-04	81.845 mi
Registration #12	2020-06-20	95.277 mi
Registration #13	2020-06-20	95.277 mi
Registration #14	2020-06-20	95.277 mi
Registration #15	2020-06-20	95.277 mi
Registration #16	2020-06-20	95.277 mi
Registration #17	2020-06-20	95.277 mi
Registration #18	2020-06-20	95.277 mi
Registration #19	2020-06-20	95.277 mi
Registration #20	2020-06-20	95.277 mi
Registration #21	2023-06-13	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5



**Number of axles**

2

**Engine number**

BBM173167