





report date: 2024-03-29

## General information

Make	MERCEDES
Model	SL SL 350 SPORT EDITION
Colour	Black
Year of manufacture	2008
Top speed	155 mph
0 - 60 mph	6.6 seconds
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	272 BHP
Max. torque	350 Nm at 2.400 rpm
Engine capacity	3.498 сс
Cylinders	6
Fuel type	Petrol
Consumption city	19.1 mpg
Consumption extra urban	36.7 mpg
Consumption combined	27.4 mpg
CO2 emission	246 g/km
CO2 label	L



CarCheck.co.uk page 1/13



report date: 2024-03-29

# Internet history

	-	4	-	2
ᆮ	п	ш	ΓV	- 3

Date	2021-11-04	
Pictures	0	
Listing price	View report	

### source: cargurus.co.uk

#### Entry 2

Date	2021-11-03
Pictures	0
Listing price	View report

### source: autotrader.co.uk

### Entry 1

Date	2021-09-01
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-04-27
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	15
Total items failed	5

MOT #18	2024-04-19 08:57
MOT test number	718351513594
Result	✓ Passed
Next expiry date	2025-04-27

MOT #17	2023-04-28 14:43
MOT test number	808114145080
Result	✓ Passed
Advice Service brake binding but not excessively Both rear (1.2.1 (f))	

MOT #16	2023-04-26 11:23
MOT test number	417389918987
Result	<b>≍</b> Failed
Advice Service brake binding but not excessively Both rear (1.2.1 (f))	
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #15	2022-04-14 12:17
MOT test number	505145086875
Result	✓ Passed

CarCheck.co.uk page 3/13



Result

YEO8KMV report date: 2024-03-29

**X** Failed

**MOT #14** 2021-04-17 11:43

MOT test number 731383880771

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #13** 2021-04-16 12:50

MOT test number 318385400473

**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #12 2020-04-11 11:24

**MOT test number** 567661471115

**Result** ✓ Passed

**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #11** 2018-11-02 17:35

**MOT test number** 424090847994

**Result** ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #10	2018-10-29 17:26
MOT test number	319566686105
Result	<b>×</b> Failed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #9	2017-11-14 16:09
MOT test number	916140051962
Result	✓ Passed
MOT #8	2017-11-10 12:21
MOT test number	194923182900
Result	<b>X</b> Failed
Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)	

MOT #7	2016-11-16 09:39
MOT test number	481339352978
Result	<b>✓</b> Passed
MOT #6	2016-06-28 13:19
MOT test number	790021770816
Result	<b>✓</b> Passed
MOT #5	2015-05-08 13:27
MOT test number	527958725156
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/13



MOT test number

Result

Notice

Under-trays fitted obscuring some underside components

Notice

O/s/r tyre worn on inner edge

MOT #3

MOT test number

Result

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay

MOT #2

MOT test number

Result

Notice N/s/f+n/s/r tyre tread uneven wear

2012-04-24 12:43

906915112154

✓ Passed

MOT #1	2011-04-21 14:05
MOT test number	878571711128
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	27 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

## Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1


Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



# Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NE NE
Plate since	
	Moro info

CarCheck.co.uk page 10/13



report date: 2024-03-29

## Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-04-21
Last registration	2024-04-19
Complete history	See info



Registration #1	2008-04-21	16 mi
Registration #2	2011-04-21	20.632 mi
Registration #3	2012-04-24	22.328 mi
Registration #4	2013-04-18	23.260 mi
Registration #5	2014-05-08	24.358 mi
Registration #6	2015-05-08	26.359 mi
Registration #7	2016-06-28	27.161 mi
Registration #8	2016-11-16	27.845 mi
Registration #9	2017-11-10	39.587 mi
Registration #10	2017-11-14	39.588 mi
Registration #11	2018-10-29	51.026 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		0.00 44

More info >

CarCheck.co.uk page 12/13



# Dimensions & weight

Width	2033 mm
Height	1317 mm
Length	4532 mm
Wheel base	2560 mm
Kerb weight	1825 kg

# Additional information

Fuel tank capacity	88 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27296630673272

CarCheck.co.uk page 13/13