





report date: 2024-03-29

General information

Make	MERCEDES
Model	B-CLASS B170 SE
Colour	Black
Year of manufacture	2006
Top speed	114 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	155 Nm at 4.000 rpm
Engine capacity	1.699 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	48.7 mpg
Consumption combined	41.5 mpg
CO2 emission	171 g/km
CO2 label	Н



CarCheck.co.uk page 1/17



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-11

Pictures 23

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/17



AK06ZXX report date: 2024-03-29

MOT history

MOT expiry date	2022-07-15
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	56
Total items failed	26

MOT #22	2021-07-12 11:30
MOT test number	925887445644
Result	✓ Passed
Next expiry date	2022-07-15

MOT #21		2020-07-16 14:26
MOT test	number	386727119132
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #20	2	2019-08-19 11:33
MOT test	number	217570799818
Result		✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Seat belt flexible stalk damaged (7.1.2 (b) (i))	
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt	
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/17



AK06ZXX report date: 2024-03-29

MOT #19 2019-08-16 11:50

MOT test number 118972158749

Result X Failed

Fail Nearside Headlamp aim too low and too far to the right. (4.1.2 (a))

Advice Offside Rear Seat belt flexible stalk damaged (7.1.2 (b) (i))

Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Headlamp aim too low (4.1.2 (a))

Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #18 2018-07-19 12:19

MOT test number 541598351957

Result

Passed

Advice Handbrake slightly insucure

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #17 2018-07-19 12:19

MOT test number 573729409978

Result × Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice Handbrake slightly insucure

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/17



report date: 2024-03-29

MOT #16 2017-12-21 11:17 **MOT test number** 890866137466 Result ✓ Passed MOT #15 2017-12-21 11:17 **MOT test number** 866229828236 Result × Failed **Pass with rectification** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4) Pass with rectification Offside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)

CarCheck.co.uk page 5/17



report date: 2024-03-29

MOT #14 2017-12-12 11:05

MOT test number 751477363984

Result X Failed

Fail Offside Headlamp aim too low (1.8)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Tyre pressure monitoring system warning lamp does not illuminate advises resetting. (4.1.D.4)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front door mirror not located on securing clips.

Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

Fail Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)

Advice Nearside Front brake pipe cover/under-tray under nearside front door damaged.

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Nearside Rear Stop lamp not working (1.2.1b)

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Offside Rear seat belt slow to retract.

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Fail Rear parking (secondary) brakes imbalanced (3.7.B.6b)

Advice Nearside Front exhaust heat shield damaged.

Advice Vehicles internal headlight adjuster altered to recheck lights

MOT #13 2016-11-30 11:28

MOT test number 169657109134

Result ✓ Passed

CarCheck.co.uk page 6/17



report date: 2024-03-29

MOT #12 2016-11-22 15:09

MOT test number 751075611962

Result X Failed

Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Nearside Rear Outer Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Stop lamp not working (1.2.1b)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Nearside Obligatory mirror insecure (8.1.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Offside Registration plate lamp not working (1.1.C.1d)

Fail Offside Headlamp aim too low (1.8)

MOT #11 2015-11-24 16:11

MOT test number 415111301812

Result

Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice One Tyre not registering on monitoring system

CarCheck.co.uk page 7/17



report date: 2024-03-29

MOT #10 2015-11-24 16:11 **MOT** test number 873835000703 Result × Failed Pass with rectification Nearside Rear Rear position lamp(s) not working (1.1.A.3b) Advice One Tyre not registering on monitoring system Pass with rectification Nearside Rear Direction indicator incorrect colour (1.4.A.2f) Advice Front Brake pad(s) wearing thin (3.5.1g) **Pass with rectification** Offside Stop lamp not working (1.2.1b) Pass with rectification Offside Rear Direction indicator incorrect colour (1.4.A.2f) **Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #9	2014-10-30 09:51
MOT test number	905943004330
Result	✓ Passed
Notice Offside rear tyre has cuts on outer sidewall	

Offside fear tyre has cuts on outer sidewall	
MOT #8	2013-10-30 11:37
MOT test number	445933903323
Result	
MOT #7	2013-10-30 09:32
MOT test number	717353703301
Result	× Failed
Fail Parking brake lever has no reserve travel (3.1.6b)	

CarCheck.co.uk page 8/17



report date: 2024-03-29

MOT #6		2012-10-20 11:54
MOT test	number	828334392237
Result		✓ Passed
Notice	Front drive shaft inner gaiters, slightly damp.	
Advice	Offside Rear Brake hose slightly deteriorated (3.6.B.4d)	
Notice	O/s/r registration lamp not working.	
Notice	Front brake discs slightly worn.	
Notice	Headlamp aim too low, o/s/f aim too slightly too far to the right.	
Advice	Offside Front Seat belt stitching slightly frayed (5.2.2b)	
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Notice	Child seat fitted not allowing full inspection of adult belt	

MOT #5		2011-10-15 12:45
MOT test	number	447188881227
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	O/s/f headlamp aim slightly too low.	
Notice	Front and rear brake discs slightly worn, scored, and pitted.	
Notice	Emissions test fast idle slight fluctuation.	

CarCheck.co.uk page 9/17



report date: 2024-03-29

MOT #4 2010-10-30 15:09 442923100483 **MOT** test number Result ✓ Passed **Notice** Child seat fitted not allowing full inspection of adult belt **Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3) Notice O/s/f tyre has a slight cut. Advice Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e) Notice Nail in nearside rear tyre Advice Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

MOT #3

MOT test number

430005330196

Result

V Passed

Notice Customer chang the number plate before the mot

MOT #2

MOT test number

933226739150

Result

✓ Passed

MOT #1

MOT test number

Result

Pass with rectification (1.2.4a)

Pass with rectification Offside Headlamp not in good working order adversely affecting beam image (3.7.B.6a)

CarCheck.co.uk page 10/17



AK06ZXX report date: 2024-03-29

See MOT history

Tax & MOT check

Tax expired: 1 May 2022



Expired: 15 July 2022 X MOT

Tax status	Expired at 1 May 2022
Days left	728 days too late
MOT expiry date	15 July 2022

Tax calculation

Full MOT history

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 11/17



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	

Date

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



report date: 2024-03-29

Owner	historv
OWNER	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloner.	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NIE NIE NIE
Plate since	
	More info >

CarCheck.co.uk page 14/17



AK06ZXX report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 15/17



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-05-16
Last registration	2021-07-12
Complete history	See info



Registration #1	2006-05-16	12 mi
Registration #2	2009-05-16	22.568 mi
Registration #3	2010-05-15	30.287 mi
Registration #4	2010-10-30	32.903 mi
Registration #5	2011-10-15	38.855 mi
Registration #6	2012-10-20	46.770 mi
Registration #7	2013-10-30	54.722 mi
Registration #8	2013-10-30	54.722 mi
Registration #9	2014-10-30	63.407 mi
Registration #10	2015-11-24	70.409 mi
Registration #11	2015-11-24	70.409 mi
Registration #12	2016-11-22	76.811 mi
	2010 11 22	
Registration #13	900-03-09	11.777 66
	999-89-89 999-89-89	11.777 es
Registration #13		11,777 ea 11,777 ea 11,777 ea
Registration #13 Registration #14		11.777 ea 11.777 ea 11.777 ea
Registration #13 Registration #14 Registration #15		11.777 es 11.777 es 11.777 es
Registration #13 Registration #14 Registration #15 Registration #16		11.777 es 11.777 es 11.777 es 11.777 es
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 16/17



AK06ZXX report date: 2024-03-29

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1310 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	54 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	26694030226718

CarCheck.co.uk page 17/17