





### General information

| Make                | PEUGEOT                          |
|---------------------|----------------------------------|
| Model               | 3008 BLUEHDI S/S GT LINE PREMIUM |
| Colour              | Red                              |
| Year of manufacture | 2018                             |
| Top speed           | 134 mph                          |
| 0 - 60 mph          | 9.0 seconds                      |
| Gearbox             | 8 speed automatic                |

### Engine & fuel consumption

| Power                   | 180 BHP             |
|-------------------------|---------------------|
| Max. torque             | 400 Nm at 2.000 rpm |
| Engine capacity         | 1.997 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 53.3 mpg            |
| Consumption extra urban | 60.1 mpg            |
| Consumption combined    | 57.7 mpg            |
| CO2 emission            | 125 g/km            |
| CO2 label               | D                   |







## Internet history

|--|

Date 2022-01-06 Pictures 36

Listing price

View report



source: autotrader.co.uk



## MOT history

| MOT expiry date    | 2024-12-19 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 3          |
| Failed MOT tests   | 0          |
| Total advice items | 4          |
| Total items failed | 0          |

| MOT #3           | 2023-12-10 11:31 |
|------------------|------------------|
| MOT test number  | 634154184233     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-12-19       |

| MOT #2   |  | 2022-12-19 10:02 |
|----------|--|------------------|
| MOT test | number   | 503429050408     |
| Result   |  | ✓ Passed         |
| Advice   | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                  |
| Advice   | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))       |                  |
| Advice   | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |
| Advice   | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))      |                  |

| MOT #1          | 2021-12-13 14:40 |
|-----------------|------------------|
| MOT test number | 352107210760     |
| Result          | ✓ Passed         |



Tax & MOT check

| √<br>Taxed               | √<br>MOT                     |
|--------------------------|------------------------------|
| Tax due:<br>1 April 2025 | Expires:<br>19 December 2024 |
| Tax status               | Valid until 1 April          |
| Days left                | 337                          |
| MOT expiry date          | 19 December 2024             |
| Full MOT history         | See MOT history              |

## Tax calculation

| Vehicle class  | 49         |
|--|------------|
| Band   | G          |
| First licence fee (12 months)                        | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months)                            | £ 180,00,- |
| Standard rate (6 months)                             | £ 99,00,-  |
| Premium rate (12 months)                             | £ 570,00,- |
| Premium rate (6 months)                              | £ 313,50,- |





### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |   |
|----------|---|
| Date     |   |
| Category | 4. DEM PE   |
| Туре     |   |
| Damage 2 | Annet   |
| Date     | No. Contraction of the second |
| Category | AMP   |
| Туре     |   |

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 6.00.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 11 711 |

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second s |             |
|---|-------------|
| **********  |             |
| *******   |             |
| ******  |             |
| **********  |             |
| *******   |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this PEUGEOT had different number plate  | 5.          |
| Number of plates  | ,           |
| Current registration  |             |
| Plate since   |             |
| Current registration  |             |
| Plate since   |             |
|   | More info > |





### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 5          |
| First mileage registration | 2018-12-20 |
| Last registration          | 2023-12-10 |
| Complete history           | See info   |



| Registration #1 | 2018-12-20 | 17 mi      |
|-----------------|------------|------------|
| Registration #2 | 2021-12-13 | 25.727 mi  |
| Registration #3 |            | 11.777 esi |
| Registration #4 |            | 11.777 est |
| Registration #5 |            | 10.307 mi  |

More info >





## Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 |                  |
| 50482 |                  |
| 50501 |                  |
| 60566 |                  |
| 60567 |                  |
| 60569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 86%             |
| Children       | 81%             |
| Pedestrian     | 31%             |
| Safety systems | 97%             |
| Overall rating | 75%             |
| Video          | see crash video |



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 1841 mm          |
| Height                            | 1624 mm          |
| Length                            | 4447 mm          |
| Wheel base                        | 2675 mm          |
| Kerb weight                       | 1480 kg          |
| Max. allowed weight               | 2090 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 53 I             |
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 5                |
| Number of seats<br>CarCheck.co.uk | 5 page 10/10     |

| Number of axles | 2           |
|-----------------|-------------|
| Engine number   | DY2T4010377 |