



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D2 ES
Colour	Black
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 2.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-12-07
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-12-16
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	12
Total items failed	5

MOT #13	2023-12-13 13:46
MOT test number	182087807276
Result	✓ Passed
Next expiry date	2024-12-16
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #12	2023-12-13 08:15
MOT test number	389198405744
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2022-12-12 10:52
MOT test number	841554359138
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**MOT #10** 2021-12-17 16:24**MOT test number** 273417827164**Result** ✓ Passed**MOT #9** 2021-08-18 13:52**MOT test number** 284422031112**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8** 2021-08-17 08:58**MOT test number** 862749381019**Result** ✗ Failed**Fail** Offside Side repeater incorrect colour unit smashed (4.4.3 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2020-08-31 10:19**MOT test number** 289804608739**Result** ✓ Passed**MOT #6** 2019-06-03 15:54**MOT test number** 680968345023**Result** ✓ Passed

**MOT #5** 2019-06-03 09:09**MOT test number** 572893233910**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 205/50r17 (5.2.3 (e))**Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 205/50r17 (5.2.3 (e))**Fail** Headlamp aim too low (4.1.2 (a))**MOT #4** 2018-05-15 11:39**MOT test number** 392096911813**Result** ✓ Passed**MOT #3** 2017-05-16 15:16**MOT test number** 813194036083**Result** ✓ Passed**MOT #2** 2017-05-16 11:34**MOT test number** 171900657893**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #1** 2016-05-23 11:59**MOT test number** 199205877741**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
16 December 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	16 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-06-12
Last registration	2023-12-13
Complete history	<a href="#">See info</a>



Registration #1	2013-06-12	29 mi
Registration #2	2016-05-23	21.443 mi
Registration #3	2017-05-16	28.398 mi
Registration #4	2017-05-16	28.398 mi
Registration #5	2018-05-15	35.618 mi
Registration #6	2019-06-03	42.860 mi
Registration #7	2019-06-03	42.860 mi
Registration #8	2020-08-31	51.203 mi
Registration #9	2020-08-31	51.203 mi
Registration #10	2020-08-31	51.203 mi
Registration #11	2020-08-31	51.203 mi
Registration #12	2020-08-31	51.203 mi
Registration #13	2020-08-31	51.203 mi
Registration #14	2020-08-31	51.203 mi
Registration #15	2020-08-31	51.203 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1519 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	2276903
---------------	---------