





report date: 2024-03-28

General information

Make	LAND ROVER
Model	FREELANDER SD4 GS
Colour	Silver
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	9.5 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 kW / 191 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 3

Date	2023-04-29	
	_	

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 2

Date	2023-04-26
Pictures	19

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2022-05-04

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



OV64FVA report date: 2024-03-28

MOT history

MOT expiry date	2024-05-24
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	11
Total items failed	4

MOT #9	2023-05-25 15:02
MOT test number	709815256137
Result	✓ Passed
Next expiry date	2024-05-24

MOT #8	2022-05-03 13:37
MOT test number	329865128482
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2021-07-22 12:29
MOT test number	802942256541
Result	✓ Passed

MOT #6		2020-07-15 10:49
MOT test	number	412528352635
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3/4 wear (5.2.3 (e))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2019-07-23 15:20 **MOT** test number 586527032396 Result **X** Failed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3/4 wear (5.2.3 (e)) **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) **Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #3

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #2
 2017-07-10 13:06

 MOT test number
 364910513758

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2017-07-04 07:59

MOT test number 798236087804

Result

x Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Front registration plate has a feature which changes the appearance or legibility of the characters (6.3.4c)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	24 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



OV64FVA report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



OV64FVA report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download to		

	More info	>
Plate changes		
See in this check if this LAND ROVER had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-10-09
Last registration	2023-05-25
Complete history	See info



Registration #1	2014-10-09	23 mi
Registration #2	2017-07-04	41.302 mi
Registration #3	2017-07-10	41.302 mi
Registration #4	2018-06-30	54.611 mi
Registration #5	2019-07-23	68.946 mi
Registration #6	2019-07-24	68.960 mi
Registration #7	2020-07-15	80.108 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		10.777 esc

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2005 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1745 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DZ784181354224DT

CarCheck.co.uk page 12/12