





report date: 2024-03-28

# General information

Make	BMW
Model	225 225XE PHEV SPORT ACTIVE TOURER
Colour	Silver
Year of manufacture	2017
0 - 60 mph	6.7 seconds
Gearbox	8 speed automatic

# Engine & fuel consumption

Power	136 BHP
Max. torque	220 Nm at 4.300 rpm
Engine capacity	1.499 сс
Cylinders	3
Fuel type	Hybrid / Electric
CO2 emission	46 g/km
CO2 label	A



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

## Entry 2

Date 2022-09-17

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2022-06-15

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

# MOT history

MOT expiry date	2024-08-24
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	13
Total items failed	6

MOT #6		2023-08-25 16:39
MOT test	number	294353111203
Result		✓ Passed
Next expiry date 2024-08-24		2024-08-24
Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))		
Advice	Rear Tyre has a cut but not deep enough to reach the ply or cords both (5.2	2.3 (d) (i))

MOT #5	2023-08-23 10:48
MOT test number	737878130440
Result	<b>≍</b> Failed
Fail Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of it (5.2.3 (d) (ii))	ts structure outer sidewall
Advice Rear Tyre has a cut but not deep enough to reach the ply or cords both	(5.2.3 (d) (i))
Fail Brake performance unable to be tested due to fail items listed (1.2.1 (g))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cor	rds (5.2.3 (d) (i))
Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

**MOT #4** 2022-06-21 08:39

**MOT test number** 188201305208

MOT #3 2021-09-28 13:08

MOT test number 441685448981

**Result** 
✓ Passed

Advice Nearside Front Tyre slightly damaged sidewall (5.2.3 (d) (ii))

MOT #2 2020-09-23 15:06

MOT test number 113474609593

**Result** 
✓ Passed

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #1** 2020-09-23 09:49

MOT test number 386953729437

Result X Failed

**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-28

# Tax & MOT check





Tax status	Valid until 1 September
Days left	125
MOT expiry date	24 August 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	59
Band	В
First licence fee (12 months)	£ 0,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

^	1000
Owner	history
	IIISCOLV

e union mistery	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	
MANAGEMENT CONTRACTOR	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NE ZIS
Plate since	
	More info >

CarCheck.co.uk page 8/11



LS67EWV

report date: 2024-03-28

### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-09-29
Last registration	2023-08-25
Complete history	See info



Registration #1	2017-09-29	26 mi
Registration #2	2020-09-23	32.023 mi
Registration #3	2020-09-23	32.025 mi
Registration #4	2021-09-28	40.266 mi
Registration #5		11.777 mi
Registration #6		0.00 44
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

# Car features

50225	Air conditioning
S0295	
S0482	
S0501	
50566	
S0567	
S0569	

# Dimensions & weight

Width	2038 mm
Height	1555 mm
Length	4342 mm
Wheel base	2670 mm
Kerb weight	1660 kg
Max. allowed weight	2180 kg

# Additional information

Fuel tank capacity	36 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	F059H594

CarCheck.co.uk page 11/11