





General information

Make	NISSAN
Model	X-TRAIL DCI TEKNA
Colour	Black
Year of manufacture	2015
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP	0 < 101 A
Max. torque	320 Nm at 1.750 rpm	101 - 120 B
Engine capacity	1.598 cc	121 - 140 P
Cylinders	4	141 - 165 F G
Fuel type	Diesel	166 - 185 H
Consumption city	44.8 mpg	186 - 225 J
Consumption extra urban	57.6 mpg	225+ L M
Consumption combined	52.3 mpg	
CO2 emission	143 g/km	
CO2 label	F	





Internet history	
Entry 1	
Date	2021-06-08
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-05
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	16
Total items failed	2

MOT #9	2024-03-28 15:39
MOT test number	412394714830
Result	✓ Passed
Next expiry date	2025-04-05
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	

MOT #8	2024-03-27 12:48	
MOT test number	343465928273	
Result	🗙 Failed	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) ((i))	

MOT #7		2023-04-06 08:59
MOT test	number	559290151010
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		





MOT #6	2023-04-01 10:26
MOT test number	478772171662
Result	🗙 Failed
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in e (5.3.4 (a) (i))	excessive movement
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in (5.3.4 (a) (i))	excessive movement
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Lower Suspension arm ball joint likely to become detached (5.3.4	1 (a) (ii))

MOT #5	2022-04-01 11:33	
MOT test number	686376954459	
Result	✓ Passed	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		

MOT #4	2021-04-01 14:58
MOT test number	483460639270
Result	✓ Passed

MOT #3		2020-03-12 08:54
MOT test	number	252645941657
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #2	2019-02-07 16:52
MOT test number	808408468901
Result	✓ Passed
MOT #1	2018-10-22 11:27
MOT test number	709075715636
Result	✓ Passed



Tax & MOT check

√ Taxed	√ MOT
Tax due: 1 July 2024	Expires: 5 April 2025
Tax status	Valid until 1 July
Days left	62
MOT expiry date	5 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-10-30
Last registration	2024-03-28
Complete history	See info



Registration #1	2015-10-30	22 mi
Registration #2	2018-10-22	33.361 mi
Registration #3	2019-02-07	34.381 mi
Registration #4	2020-03-12	52.860 mi
Registration #5	2021-04-01	62.104 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi





Car features

50225	Air conditioning
50295	
50482	
60501	
60566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	86%
Children	83%
Pedestrian	75%
Safety systems	75%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1820 mm
Height	1710 mm
Length	4640 mm
Wheel base	2705 mm
Kerb weight	1610 kg
Max. allowed weight	2320 kg
Additional information	
Fuel tank capacity	60
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12