





report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD VTEC EX
Colour	Silver
Year of manufacture	2006
Top speed	134 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	153 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	23.2 mpg
Consumption extra urban	44.8 mpg
Consumption combined	33.6 mpg
CO2 emission	200 g/km
CO2 label	J



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-23

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

	~		
10/1/	1	hic	tory
- 1010	,, ,	1115	IUIV
	<i>-</i> .		

MOT expiry date	2025-02-04
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	17
Total items failed	3

MOT #17	2024-02-05 15:12
MOT test number	419687468946
Result	✓ Passed
Next expiry date	2025-02-04

MOT #16	20	022-08-12 13:17
MOT test	number	363653834429
Result		✓ Passed
Advice	Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b)	(i))
Advice	Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened O/S $\&$ N/S (1.1.1	4 (a) (ii))

CarCheck.co.uk page 3/13



RE560CG

report date: 2024-03-28

MOT #15		2021-08-18 16:23
MOT test	number	246054178043
Result		✓ Passed
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 ((b) (i))
Advice Front Bush	Offside Front Lower Suspension arm pin or bush worn but not resulting in en (5.3.4 (a) (i))	excessive movement
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3	3 (b) (i))
Advice Front Bush	Nearside Front Lower Suspension arm pin or bush worn but not resulting in $(5.3.4 (a) (i))$	excessive movement

MOT #14	2020-08-18 15:55
MOT test number	473516150691
Result	✓ Passed
MOT #13	2019-07-31 11:57
MOT test number	249356457807
Result	✓ Passed
MOT #12	2018-08-02 09:30
MOT test number	196694962437
Result	✓ Passed
MOT #11	2017-08-24 14:53
MOT test number	687935289836
Result	✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #10

MOT test number

221118810060

Result

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

 MOT #9
 2015-08-11 09:57

 MOT test number
 367213425254

 Result
 ✓ Passed

 MOT #8
 2015-08-10 15:40

 MOT test number
 786702625236

 Result
 X Failed

 Fail
 Offside Front Anti-roll bar linkage worn and seriously weakened (2.4.G.1)

MOT #7

MOT test number

405824524208

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT test number

459293324227

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Front Anti-roll bar linkage fractured (2.4.G.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Rear brake disc in such a condition that it is seriously weakened (3.5.1i)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #5	2013-08-28 10:41
MOT test number	166070543293
Result	✓ Passed
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
MOT #4	2012-09-06 16:23
MOT test number	197810752268
Result	✓ Passed
MOT #3	2011-09-05 11:51
MOT test number	198438341247
Result	✓ Passed
MOT #2	2010-09-08 15:02
MOT test number	743431650203
Result	✓ Passed
MOT #1	2009-09-22 09:55
MOT test number	622735669206
Result	/ Passed

MOT #1	2009-09-22 09:55
MOT test number	622735669206
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	4 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



RE560CG

report date: 2024-03-28

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

RE56OCG

report date: 2024-03-28

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

See in this check if this HONDA had different number plates.

More info >

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-09-28
Last registration	2024-02-05
Complete history	See info



Registration #1	2006-09-28	12 mi
Registration #2	2009-09-22	27.658 mi
Registration #3	2010-09-08	34.869 mi
Registration #4	2011-09-05	43.228 mi
Registration #5	2012-09-06	51.126 mi
Registration #6	2013-08-28	56.075 mi
Registration #7	2014-08-11	63.433 mi
Registration #8	2014-08-12	63.433 mi
Registration #9	2015-08-10	70.639 mi
Registration #10	2015-08-11	70.639 mi
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		11.177 mi
Registration #14		11.777 es
Registration #15		11.177 mi
Registration #16		11.777 es
Registration #17		11.177 mi
Registration #18		11.777 es
Registration #19		10.777 au

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm
Kerb weight	1401 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Engine number	K20Z21108111

CarCheck.co.uk page 13/13