





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF MATCH TSI EVO
Colour	Grey
Year of manufacture	2019
Top speed	130 mph
0 - 100 km/h	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	96 kW / 131 HP / 128 BHP
Max. torque	200 Nm at 1.400 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.4 mpg
Consumption combined	47.1 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date	2022-05-09
------	------------

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date	2022-04-05	
Pictures	1	
Listing price	View report	



source: cargurus.co.uk

CarCheck.co.uk page 2/11



FN19MXZ report date: 2024-03-28

MAGE	
MOL	history
	IIISLUI V

MOT expiry date	2025-02-12
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	10
Total items failed	0

MOT #4		2024-02-12 10:26
MOT test	number	717784807265
Result		✓ Passed
Next expi	ry date	2025-02-12
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Side repeater slightly discoloured (4.4.3 (a))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 205/55/16 (5.2.3 (e))	

MOT #3	2023-02-13 11:35
MOT test number	182551379465
Result	✓ Passed

MOT #2	2022-03-28 09:46
MOT test number	149875935771
Result	✓ Passed
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d)	(ii))
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2022-03-18 12:26

MOT test number 997837476846

Result ★ Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

CarCheck.co.uk page 4/11



FN19MXZ report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	12 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11




report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra VOLKSWAGEN salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner	history
OWITCE	iliotoi y

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-03-14
Last registration	2024-02-12
Complete history	See info



Registration #1	2019-03-14	22 mi
Registration #2	2022-03-18	38.114 mi
Registration #3	2022-03-28	38.114 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



FN19MXZ report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	89%
Pedestrian	65%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2027 mm
Height	1492 mm
Length	4258 mm
Wheel base	2620 mm
Kerb weight	1215 kg

Additional information

Fuel tank capacity	50 I
Number of axles	2
Engine number	DACA208870

CarCheck.co.uk page 11/11