



**LG05KGK**


report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE V6
Colour	Silver
Year of manufacture	2005
Top speed	127 mph
0 - 60 mph	10.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	157 BHP
Max. torque	200 Nm at 4.100 rpm
Engine capacity	2.099 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.8 mpg
Consumption extra urban	38.2 mpg
Consumption combined	28.3 mpg
CO2 emission	239 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-11-26
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-20
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	26
Total items failed	15

MOT #232023-05-21 12:07

MOT test number478231500013

Result✓ Passed

Next expiry date2024-05-20

- Advice**Oil leak, but not excessive (8.4.1 (a) (i))
- Advice**Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice**Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice**Offside Rear Nail in tyre
- Advice**Rear Coil spring corroded Both sides (5.3.1 (b) (i))
- Advice**Rear Shock absorbers has light misting of oil Both sides (5.3.2 (b))
- Advice**Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice**Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

**MOT #22**

2023-04-15 15:28

**MOT test number**

801475018970

**Result****✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Front Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))**Advice** Nearside Rear Suspension arm damaged but not seriously weakened trail arm distorted (5.3.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge edges cracking (5.2.3 (e))**Fail** Offside Headlamp aim too low (4.1.2 (a))**Minor** Offside Rear fog lamp lens defective which has no effect on emitted light (4.5.1 (b) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #21**

2021-12-13 14:12

**MOT test number**

143987780388

**Result****✓ Passed****MOT #20**

2020-12-09 08:52

**MOT test number**

367510081566

**Result****✓ Passed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19** 2020-12-09 08:41**MOT test number** 694698645317**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #18** 2019-12-02 11:58**MOT test number** 354232527489**Result** ✓ Passed**MOT #17** 2018-12-05 16:28**MOT test number** 585178995313**Result** ✓ Passed**Advice** Front Inner Both front tyres wearing heavily on inner edge of tread**MOT #16** 2017-12-04 14:04**MOT test number** 611918742007**Result** ✓ Passed**Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #15** 2016-12-06 17:24**MOT test number** 635294993765**Result** ✓ Passed

**MOT #14** 2016-01-09 11:48**MOT test number** 166226300620**Result** ✓ Passed**Advice** Nearside Front Outer Front passenger door catch deteriorated but the door can still be readily opened and closed (6.2.B.2)**Advice** Front Tyre worn close to the legal limit tyres (4.1.E.1)**MOT #13** 2016-01-09 11:48**MOT test number** 258079440865**Result** ✗ Failed**Advice** Front Tyre worn close to the legal limit tyres (4.1.E.1)**Pass with rectification** Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Outer Front passenger door catch deteriorated but the door can still be readily opened and closed (6.2.B.2)**MOT #12** 2014-12-31 10:40**MOT test number** 835795964307**Result** ✓ Passed**Notice** Oil leak**MOT #11** 2013-12-28 15:21**MOT test number** 756642763323**Result** ✓ Passed**Notice** Oil leak**MOT #10** 2012-12-31 12:23**MOT test number** 548746862309**Result** ✓ Passed

**MOT #9** 2012-12-31 12:23**MOT test number** 908846262313**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #8** 2011-12-30 12:50**MOT test number** 425044161467**Result** ✓ Passed**MOT #7** 2011-12-30 12:50**MOT test number** 167794661346**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2010-12-30 10:34**MOT test number** 220044160399**Result** ✓ Passed**MOT #5** 2010-12-29 11:23**MOT test number** 833323960339**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Fail** Nearside Headlamp aim too high (1.8)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Front registration plate deteriorated (6.3.1d)



MOT #4	2009-12-31 12:59
MOT test number	583925969307
Result	✓ Passed
MOT #3	2008-12-30 17:22
MOT test number	154515468362
Result	✗ Failed
<div>Pass with rectification</div> Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
MOT #2	2008-12-30 17:22
MOT test number	442525768485
Result	✓ Passed
MOT #1	2007-12-19 11:14
MOT test number	360313657398
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
20 May 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	367
<b>MOT expiry date</b>	20 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-03-01
Last registration	2023-05-21
Complete history	<a href="#">See info</a>



Registration #1	2005-03-01	6 mi
Registration #2	2007-12-19	20.731 mi
Registration #3	2008-12-30	26.616 mi
Registration #4	2009-12-31	34.371 mi
Registration #5	2010-12-29	39.650 mi
Registration #6	2010-12-30	39.650 mi
Registration #7	2011-12-30	44.862 mi
Registration #8	2012-12-31	53.803 mi
Registration #9	2013-12-28	64.558 mi
Registration #10	2014-12-31	67.562 mi
Registration #11	2016-01-09	70.649 mi
Registration #12	2016-01-09	70.649 mi
Registration #13	2016-01-09	70.649 mi
Registration #14	2016-01-09	70.649 mi
Registration #15	2016-01-09	70.649 mi
Registration #16	2016-01-09	70.649 mi
Registration #17	2016-01-09	70.649 mi
Registration #18	2016-01-09	70.649 mi
Registration #19	2016-01-09	70.649 mi
Registration #20	2016-01-09	70.649 mi
Registration #21	2016-01-09	70.649 mi
Registration #22	2016-01-09	70.649 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1485 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	515020427YB