





report date: 2024-03-28

## General information

Make	MERCEDES-BENZ
Model	ML ML270 CDI SPECIAL EDITION
Colour	Blue
Year of manufacture	-
Top speed	114 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	161 BHP
Max. torque	370 Nm at 1.800 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	37.2 mpg
Consumption combined	31.0 mpg



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-07-11

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

### **MOT** history

MOT #17

MOT test number

443281286835

Result

Advice

Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4)

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Fail Nearside Rear Brake pipe leaking on an air braking system (1.1.11 (b) (i))

**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Rear Service brake has no recorded effort at a wheel (1.2.1 (a) (ii))

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Fail

Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Nearside Rear Service brake has no recorded effort at a wheel (1.2.1 (a) (ii))

Minor Offside Front Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #16 2020-08-19 13:58

MOT test number 516830516670

Result ✓ Passed

MOT #15

MOT test number

480321575018

Result

Passed

MOT #14 2019-02-04 15:16

**MOT test number** 150729850988

Result × Failed

Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Rear Suspension arm has slight play in a ball joint (2.4.G.2)

Advice

Offside Rear tyre wall cracking

MOT #12

MOT test number

Result

MOT #11

MOT test number

2017-02-14 14:33

MOT test number

330769715625

Result

Fail Offside Rear Anti-roll bar has excessive play in a ball joint missing (2.4.G.2)

MOT test number

Result

Advice Offside Rear Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Nearside Rear Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Offside Front Outer Anti-roll bar rubber bush deteriorated but not resulting in excessive movement d bush (2.4.G.2)

MOT #9

MOT test number

Result

Advice

Offside Front Track rod end ball joint has slight play (2.2.B.1f)

Advice
(2.4.G.2)

Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Advice Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Advice Steering system has slight free play detected at steering wheel (2.2.A.1b)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #6

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

 MOT #5
 2010-12-30 10:25

 MOT test number
 130014860353

 Result
 ✓ Passed

MOT test number

### Advice 
### Exhaust has a minor leak of exhaust gases (7.1.2)

### Notice 
### Slight wear to all 4 tyres

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT #3	2008-12-08 14:13
MOT test number	254733248383
Result	✓ Passed
MOT #2	2008-12-05 10:31
MOT test number	604700548356
Result	<b>×</b> Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Offside Rear Stop lamp not working (1.2.1b)	
Fail Offside Rear coil spring fractured (2.4.C.1a)	

MOT #1		2007-12-22 10:06
MOT test	number	981666757393
Result		✓ Passed
Advice	Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)	
Notice	Slight free play in front & rear bottom ball joints.	

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra MERCEDES-BENZ salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this MERCEDES-BENZ had different number plates. mber of plates -More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-12-24
Last registration	2021-08-28
Complete history	See info



Registration #1	2004-12-24	14 mi
Registration #2	2007-12-22	81.658 mi
Registration #3	2008-12-05	107.407 mi
Registration #4	2008-12-08	107.410 mi
Registration #5	2010-01-30	138.482 mi
Registration #6	2010-12-30	147.540 mi
Registration #7	2012-01-07	153.757 mi
Registration #8	2013-01-21	161.638 mi
Registration #9	2014-01-28	168.180 mi
Registration #10	2015-01-21	173.473 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

\$0295 \$0482 \$0501 \$0566	
S0501 S0566	
50566	
60567	
60569	
S0569 /iew the complete MERCEDES-BENZ factory list for this	

		_		
llima	ensior	וכ אי	WAIN	nт
		IS CX	WEIG	116

Width	2126 mm
Height	1820 mm
Length	4638 mm
Wheel base	2820 mm
Max. allowed weight	2870 kg

# Additional information

Fuel tank capacity	83 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	61296330338647

CarCheck.co.uk page 12/12