



HYUNDAI



report date: 2024-03-29

General information

|                     |                   |
|---------------------|-------------------|
| Make                | HYUNDAI           |
| Model               | I40 CRDI PREMIUM  |
| Colour              | Black             |
| Year of manufacture | 2013              |
| Top speed           | 122 mph           |
| 0 - 60 mph          | 11.6 seconds      |
| Gearbox             | 6 speed automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 134 BHP             |
| Max. torque             | 325 Nm at 2.500 rpm |
| Engine capacity         | 1.685 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 37.2 mpg            |
| Consumption extra urban | 55.4 mpg            |
| Consumption combined    | 47.1 mpg            |
| CO2 emission            | 159 g/km            |
| CO2 label               | G                   |





Internet history

Entry 3


|               |                             |
|---------------|-----------------------------|
| Date          | 2024-01-12                  |
| Pictures      | 44                          |
| Listing price | <a href="#">View report</a> |



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2

|               |                             |
|---------------|-----------------------------|
| Date          | 2023-10-26                  |
| Pictures      | 9                           |
| Listing price | <a href="#">View report</a> |



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-07-02                  |
| Pictures      | 0                           |
| Listing price | <a href="#">View report</a> |

source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-07-02 |
| MOT pass rate      | 80 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 2          |
| Total advice items | 18         |
| Total items failed | 6          |

|                  |   |
|------------------|---|
| MOT #10          | 2023-06-29 11:48  |
| MOT test number  | 508794750328  |
| Result           | ✓ Passed  |
| Next expiry date | 2024-07-02  |
| Advice           | Rear Tyre worn close to legal limit/worn on edge O/S & N/S. Bald on inner shoulders (5.2.3 (e))             |
| Minor            | Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |

|                 |   |
|-----------------|---|
| MOT #9          | 2022-06-21 10:38  |
| MOT test number | 607529749896  |
| Result          | ✓ Passed  |
| Advice          | Driver's view Items removed from driver's view prior to test phoneholder from windscreen (3.1 (a) (ii)) |
| Advice          | Undertray fitted preventing full inspection of some components  |
| Advice          | Vehicles internal headlight adjuster altered to recheck lights  |
| Advice          | Nearside Rear Tyre worn close to legal limit/worn on edge 2mm tread (5.2.3 (e))                         |

**MOT #8**

2022-06-20 14:05

**MOT test number**

597781437108

**Result****✗ Failed****Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Fail** Offside Front Brake disc in such a condition that it is seriously weakened heavily scored (1.1.14 (a) (ii))**Advice** Undertray fitted preventing full inspection of some components**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm tread (5.2.3 (e))**Advice** Driver's view Items removed from driver's view prior to test phoneholder from windscreen (3.1 (a) (ii))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick metal 2 metal (1.1.13 (a) (ii))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #7**

2021-07-03 13:59

**MOT test number**

241002593040

**Result****✓ Passed****Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6**

2020-09-11 10:53

**MOT test number**

248720930940

**Result****✓ Passed****Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #5** 2019-08-23 15:07**MOT test number** 494265339287**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge on 2.8mm (5.2.3 (e))**MOT #4** 2019-08-23 09:39**MOT test number** 443373129622**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed 9 inch split in tread (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on 2.8mm (5.2.3 (e))**MOT #3** 2018-08-31 13:33**MOT test number** 485237691849**Result** ✓ Passed**MOT #2** 2017-09-15 09:56**MOT test number** 512008623935**Result** ✓ Passed**MOT #1** 2016-05-28 10:10**MOT test number** 675255658111**Result** ✓ Passed**Advice** Brake fluid level low**Advice** Cut in nearside front tyre**Advice** Rear brake pads low



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
2 July 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 February          |
| <b>Days left</b>        | 279                             |
| <b>MOT expiry date</b>  | 2 July 2024                     |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | G          |
| <b>Single payment (12 months)</b>              | £ 240,00,- |
| <b>Single six month payment</b>                | £ 132,00,- |
| <b>Total payable by 12 monthly instalments</b> | £ 252,00,- |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 15,200 |
| Auction value               | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2024-03-29 |
| Current registration |            |
| Plate since          | 2024-03-29 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 14                       |
| First mileage registration | 2013-06-26               |
| Last registration          | 2023-06-29               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2013-06-26 | 27 mi     |
| Registration #2  | 2016-05-28 | 74.059 mi |
| Registration #3  | 2017-09-15 | 33.093 mi |
| Registration #4  | 2018-08-31 | 38.045 mi |
| Registration #5  | 2019-08-23 | 51.154 mi |
| Registration #6  | 2019-08-23 | 51.154 mi |
| Registration #7  | 2020-09-11 | 63.908 mi |
| Registration #8  | 2020-09-11 | 63.908 mi |
| Registration #9  | 2020-09-11 | 63.908 mi |
| Registration #10 | 2020-09-11 | 63.908 mi |
| Registration #11 | 2020-09-11 | 63.908 mi |
| Registration #12 | 2020-09-11 | 63.908 mi |
| Registration #13 | 2020-09-11 | 63.908 mi |
| Registration #14 | 2020-09-11 | 63.908 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 92%                             |
| Children       | 86%                             |
| Pedestrian     | 43%                             |
| Safety systems | 86%                             |
| Overall rating | 80%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1815 mm |
| Height              | 1470 mm |
| Length              | 4740 mm |
| Wheel base          | 2770 mm |
| Kerb weight         | 1601 kg |
| Max. allowed weight | 2100 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 70 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 4                |
| Number of seats    | 5                |

|                        |              |
|------------------------|--------------|
| <b>Number of axles</b> | 2            |
| <b>Engine number</b>   | D4FDDU320988 |