



PEUGEOT



report date: 2024-03-28

General information

|                     |                     |
|---------------------|---------------------|
| Make                | PEUGEOT             |
| Model               | 307 COUPE CABRIOLET |
| Colour              | Grey                |
| Year of manufacture | -                   |
| Top speed           | 129 mph             |
| 0 - 60 mph          | 10.3 seconds        |
| Gearbox             | 5 speed Manual      |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 134 BHP             |
| Max. torque             | 190 Nm at 4.100 rpm |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 24.6 mpg            |
| Consumption extra urban | 45.6 mpg            |
| Consumption combined    | 34.0 mpg            |



LABEL UNKNOWN



Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-12-03                  |
| Pictures      | 0                           |
| Listing price | <a href="#">View report</a> |

source: [autotrader.co.uk](#)

**MOT history**

|                         |   |
|-------------------------|---|
| <b>MOT #18</b>          | 2021-02-16 16:17  |
| <b>MOT test number</b>  | 328371633789  |
| <b>Result</b>           | ✓ Passed  |
| <b>Next expiry date</b> | 2022-02-15  |
| <b>Advice</b>           | Front Track rod end ball joint has slight play both (2.1.3 (b) (i))   |
| <b>Advice</b>           | Slight corrosion under body   |
| <b>Minor</b>            | Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| <b>Advice</b>           | Oil leak, but not excessive (8.4.1 (a) (i))   |

|                        |  |
|------------------------|--|
| <b>MOT #17</b>         | 2021-02-11 14:48   |
| <b>MOT test number</b> | 890785810839   |
| <b>Result</b>          | ✗ Failed   |
| <b>Minor</b>           | Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))              |
| <b>Fail</b>            | Front Headlamp has a product on the light source which changes emitted colour to other than white or yellow both (4.1.4 (b)) |
| <b>Fail</b>            | Central Front Exhaust has a major leak of exhaust gases middle box (6.1.2 (a))   |
| <b>Advice</b>          | Front Track rod end ball joint has slight play both (2.1.3 (b) (i))  |
| <b>Fail</b>            | Front Headlamp aim projected beam image is obviously incorrect both (4.1.2 (c))  |
| <b>Advice</b>          | Oil leak, but not excessive (8.4.1 (a) (i))  |
| <b>Fail</b>            | Front Brake disc significantly and obviously worn (1.1.14 (a) (i))   |
| <b>Fail</b>            | Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))  |
| <b>Advice</b>          | Slight corrosion under body  |
| <b>Fail</b>            | Front Direction indicator not working both (4.4.1 (a) (ii))  |

**MOT #16** 2020-02-07 08:35**MOT test number** 105151324152**Result** ✓ Passed

- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin N/S & O/S (1.1.13 (a) (ii))

**MOT #15** 2019-02-13 16:58**MOT test number** 854855129984**Result** ✓ Passed**MOT #14** 2018-04-09 12:22**MOT test number** 717676355993**Result** ✓ Passed**MOT #13** 2018-04-09 12:22**MOT test number** 825866087507**Result** ✗ Failed

- Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #12** 2017-04-07 12:01**MOT test number** 189579108062**Result** ✓ Passed

**MOT #11** 2016-04-12 08:42**MOT test number** 453340369878**Result** ✓ Passed**Advice** Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Nearside Rear brake slightly binding**MOT #10** 2015-04-08 10:55**MOT test number** 859688795047**Result** ✓ Passed**Notice** N/s/r tyre worn bald on outer edge**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Ball joint has slight play (2.2.B.1f)**Advice** Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-03-26 14:50**MOT test number** 826045884012**Result** ✓ Passed**Notice** O/s steering track arm has slight play in ball joint**MOT #8** 2014-03-26 13:16**MOT test number** 728655684018**Result** ✗ Failed**Notice** O/s steering track arm has slight play in ball joint**Fail** Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #7** 2013-04-15 10:36**MOT test number** 227615103104**Result** ✓ Passed**MOT #6** 2013-01-16 15:21**MOT test number** 218946413068**Result** ✓ Passed**MOT #5** 2013-01-15 10:07**MOT test number** 668765513043**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2011-06-23 17:11**MOT test number** 278474671123**Result** ✓ Passed**MOT #3** 2009-12-01 13:13**MOT test number** 671495039390**Result** ✓ Passed**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** O/s/r brake binding**MOT #2** 2008-08-18 15:42**MOT test number** 333051538289**Result** ✓ Passed



|                         |  |
|-------------------------|--|
| MOT #1                  | 2008-08-18 15:42                                   |
| MOT test number         | 852251438286                                       |
| Result                  | ✗ Failed   |
| Pass with rectification | Front Brake pad(s) less than 1.5 mm thick (3.5.1g) |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>KF05TFK</b> |
| Plate since          | 2019-03-28     |
| Current registration | <b>KF05TFK</b> |
| Plate since          | 2019-03-28     |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 19                       |
| First mileage registration | 2005-04-13               |
| Last registration          | 2021-02-16               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2005-04-13 | 24 mi     |
| Registration #2  | 2008-08-18 | 32.150 mi |
| Registration #3  | 2009-12-01 | 38.007 mi |
| Registration #4  | 2011-06-23 | 45.632 mi |
| Registration #5  | 2013-01-15 | 45.701 mi |
| Registration #6  | 2013-01-16 | 45.707 mi |
| Registration #7  | 2013-04-15 | 45.720 mi |
| Registration #8  | 2014-03-26 | 59.562 mi |
| Registration #9  | 2014-03-26 | 59.562 mi |
| Registration #10 | 2015-04-08 | 70.505 mi |
| Registration #11 | 2015-05-20 | 75.377 mi |
| Registration #12 | 2015-05-20 | 75.377 mi |
| Registration #13 | 2015-05-20 | 75.377 mi |
| Registration #14 | 2015-05-20 | 75.377 mi |
| Registration #15 | 2015-05-20 | 75.377 mi |
| Registration #16 | 2015-05-20 | 75.377 mi |
| Registration #17 | 2015-05-20 | 75.377 mi |
| Registration #18 | 2015-05-20 | 75.377 mi |
| Registration #19 | 2015-05-20 | 75.377 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1759 mm |
| Height              | 1423 mm |
| Length              | 4349 mm |
| Wheel base          | 2605 mm |
| Kerb weight         | 1457 kg |
| Max. allowed weight | 1830 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 60 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 2                     |
| Number of seats    | 4                     |

|                 |             |
|-----------------|-------------|
| Number of axles | 2           |
| Engine number   | LH1Z1197563 |