



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 AIRPLAY PLUS
Colour	Black
Year of manufacture	-
Top speed	98 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-29
Pictures	3
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT #17	2023-01-17 09:36
MOT test number	562528422473
Result	✓ Passed
Next expiry date	2024-01-16
Advice	Oil leak, but not excessive sump corroded and leaking (8.4.1 (a) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #16	2022-01-17 17:28
MOT test number	372811692465
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #15	2022-01-10 16:56
MOT test number	569185559331
Result	✗ Failed
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened worn/pitted (1.1.14 (a) (ii))
Advice	Items removed from driver's view prior to test
Fail	Nearside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Fail	Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))
Advice	Tyre worn close to legal limit/worn on edge both rear at 3mm and cracking in tread (5.2.3 (e))
Advice	Nearside Front outer sill holed and corroded

**MOT #14** 2021-01-13 14:34**MOT test number** 186382353670**Result** ✓ Passed

- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** N/s sill area damaged
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13 2019-11-11 15:15**MOT test number** 863571014225**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Both rear bump stops missing
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #12 2018-11-10 13:06**MOT test number** 711648239276**Result** ✓ Passed**MOT #11** 2017-11-11 08:38**MOT test number** 374195087547**Result** ✓ Passed

**MOT #10** 2016-11-11 12:18**MOT test number** 994346572306**Result** ✓ Passed**MOT #9** 2016-11-11 09:07**MOT test number** 477025770441**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**MOT #8** 2015-11-18 13:35**MOT test number** 815090938678**Result** ✓ Passed**MOT #7** 2015-11-16 15:50**MOT test number** 822377053762**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Rear Exhaust system not adequately supported (7.1.1)**MOT #6** 2014-10-01 13:37**MOT test number** 396664774235**Result** ✓ Passed**Notice** Spare tyre flat.**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #5** 2013-08-08 12:48**MOT test number** 737660323225**Result** ✓ Passed**MOT #4** 2012-01-11 14:41**MOT test number** 426101412056**Result** ✓ Passed**Notice** Nail o/s/f tyre**MOT #3** 2012-01-11 13:04**MOT test number** 215661512045**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Rear rear brake recording little or no effort (3.7.B.5a)**Notice** Nail o/s/f tyre**Fail** Nearside Front Tie bar/rod has excessive play in a ball joint (2.4.G.2)**MOT #2** 2011-01-19 12:54**MOT test number** 335309011083**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2010-01-25 15:18**MOT test number** 143635920010**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,200
Auction value	£ 19,200
Average private trade value	£ 19,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-01-27
Last registration	2023-01-17
Complete history	See info



Registration #1	2007-01-27	18 mi
Registration #2	2010-01-25	54.984 mi
Registration #3	2011-01-19	53.638 mi
Registration #4	2012-01-11	17.450 mi
Registration #5	2012-01-11	61.860 mi
Registration #6	2013-08-08	67.434 mi
Registration #7	2014-10-01	68.698 mi
Registration #8	2015-11-16	70.689 mi
Registration #9	2015-11-18	70.695 mi
Registration #10	2016-11-11	73.494 mi
Registration #11	2016-11-11	73.494 mi
Registration #12	2016-11-11	73.494 mi
Registration #13	2016-11-11	73.494 mi
Registration #14	2016-11-11	73.494 mi
Registration #15	2016-11-11	73.494 mi
Registration #16	2016-11-11	73.494 mi
Registration #17	2016-11-11	73.494 mi
Registration #18	2016-11-11	73.494 mi
Registration #19	2016-11-11	73.494 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1477 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	932 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7W4926126