





report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	2013
Top speed	113 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	42.2 mpg
Consumption combined	35.3 mpg
CO2 emission	211 g/km
CO2 label	K



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date	2021-02-05	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



LR63AMX report date: 2024-03-28

MOT history

MOT expiry date	2024-09-04
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	6
Total items failed	8

MOT #13	2023-09-05 14:20
MOT test number	204626788311
Result	✓ Passed
Next expiry date	2024-09-04

MOT #12	2023-08-24 14:59
MOT test number	636644135398
Result	× Failed
Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	

MOT #11		2022-08-02 17:12
MOT test	number	178486028332
Result		✓ Passed
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10 2022-08-02 17:12

MOT test number 908182478063

Result X Failed

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Pass with rectification Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9 2021-08-23 15:04

MOT test number 768224761768

Result ✓ Passed

MOT #8 2021-08-20 17:58

MOT test number 928925381674

Result X Failed

Fail Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))

Fail Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))

MOT #7 2020-12-01 12:09

MOT test number 626344401936

Result

Passed

MOT #6 2020-11-30 12:34

MOT test number 544779976745

Result X Failed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2019-06-13 09:59

MOT test number 708255223011

MOT #4 2019-06-13 09:59

MOT test number 504285061351

Result X Failed

Pass with rectification Nearside Front Drive shaft joint constant velocity boot split or insecure, no

longer prevents the ingress of dirt (6.1.7 (g) (ii))

Pass with rectification Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #3 2018-07-04 09:31

MOT test number 590353515435

Result ✓ Passed

MOT #2 2017-07-06 08:43

MOT test number 814433206890

MOT #1 2016-10-06 09:21

MOT test number 398918959386

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	4 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	

Plate changes	More info >
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-10-08
Last registration	2023-09-05
Complete history	See info



Registration #1	2013-10-08	18 mi
Registration #2	2016-10-06	17.665 mi
Registration #3	2017-07-06	19.905 mi
Registration #4	2018-07-04	28.258 mi
Registration #5	2019-06-13	37.518 mi
Registration #6	2019-06-13	37.518 mi
Registration #7	2020-11-30	42.225 mi
Registration #8	2020-12-01	42.228 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		91,700 esi
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 11/12



LR63AMX report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1936 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 286966K LNQ

CarCheck.co.uk page 12/12