




report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	White
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 4

Date	2023-12-06
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

Entry 3

Date	2023-07-24
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

Entry 2


Date	2023-07-19
Pictures	20
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-30
Pictures	22
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-05
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	10
Total items failed	5

<b>MOT #13</b>	2023-07-06 13:05
MOT test number	234213496109
Result	✓ Passed
Next expiry date	2024-07-05

<b>MOT #12</b>	2023-07-05 11:26
MOT test number	659675300889
Result	✗ Failed
<p><b>MAJOR</b> Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))</p> <p><b>DANGEROUS</b> Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))</p> <p><b>DANGEROUS</b> Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))</p> <p><b>MAJOR</b> Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))</p>	

<b>MOT #11</b>	2022-10-13 10:00
MOT test number	176445176667
Result	✓ Passed

<b>MOT #10</b>	2021-09-09 14:52
MOT test number	399507812936
Result	✓ Passed



**MOT #9** 2021-09-09 14:52

**MOT test number** 857532146605

**Result** ✗ Failed

- Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Pass with rectification** Front Registration plate inscription illegible (0.1 (b))
- Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #8** 2020-12-18 13:15

**MOT test number** 686068329309

**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside parking brake requires service/ adjustment

**MOT #7** 2020-12-15 11:26

**MOT test number** 360035844106

**Result** ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside parking brake requires service/ adjustment
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #6** 2019-12-06 14:52

**MOT test number** 570720831483

**Result** ✓ Passed

**MOT #5** 2018-12-05 14:44

**MOT test number** 482658957891

**Result** ✓ Passed



<b>MOT #4</b>	2017-12-01 15:12
<b>MOT test number</b>	250184149080
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2017-12-01 15:12
<b>MOT test number</b>	751507879188
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Windscreen washer provides insufficient washer liquid (8.2.3)
<b>Pass with rectification</b>	Nearside Front position lamp(s) not working (1.1.A.3b)

<b>MOT #2</b>	2017-01-30 10:54
<b>MOT test number</b>	228993329247
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Tyre worn close to the legal limit x2 (4.1.E.1)

<b>MOT #1</b>	2016-01-18 10:27
<b>MOT test number</b>	631602510781
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 January 2025

✓  
**MOT**

**Expires:**  
5 July 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	5 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



## Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-09-29
Current registration	XXXXX
Plate since	2019-09-29

More info >



**Finance check**

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


<b>Finance company</b>	XXXXXXXX XX
<b>Date of agreement</b>	XXXXXXXX XX
<b>Agreement type</b>	XXXXXXXX XX
<b>Agreement term</b>	XXXXXXXX XX
<b>Agreement number</b>	XXXXXXXX XX
<b>Contact info</b>	XXXXXXXX XX

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2013-01-31
Last registration	2023-07-06
Complete history	<a href="#">See info</a>



Registration #1	2013-01-31	23 mi
Registration #2	2016-01-18	61.220 mi
Registration #3	2017-01-30	72.797 mi
Registration #4	2017-12-01	78.865 mi
Registration #5	2017-12-01	78.865 mi
Registration #6	2018-12-05	86.704 mi
Registration #7	2019-12-06	94.398 mi
Registration #8	2020-12-15	97.346 mi
Registration #9	2020-12-18	97.376 mi
Registration #10		
Registration #11		
Registration #12		
Registration #13		
Registration #14		
Registration #15		
Registration #16		
Registration #17		
Registration #18		

[More info >](#)



## Safety ratings

<b>NCAP rating</b>	★★★★★
<b>Adult</b>	95%
<b>Children</b>	84%
<b>Pedestrian</b>	46%
<b>Safety systems</b>	71%
<b>Overall rating</b>	81%
<b>Video</b>	<a href="#">see crash video</a>



## Dimensions & weight

<b>Width</b>	2085 mm
<b>Height</b>	1717 mm
<b>Length</b>	4596 mm
<b>Wheel base</b>	2707 mm
<b>Kerb weight</b>	1896 kg
<b>Max. allowed weight</b>	2505 kg

## Additional information

<b>Fuel tank capacity</b>	65 l
<b>Fuel delivery</b>	Direct Injection
<b>Number of doors</b>	5
<b>Number of seats</b>	5
<b>Number of axles</b>	2
<b>Engine number</b>	Z22D1 291601K LNQ