




report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVARO 2900 L2H1 CDTi P/V
Colour	White
Year of manufacture	2016
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	49.5 mpg
Consumption combined	43.5 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-21
Pictures	13
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-10-12
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	12
Total items failed	5

MOT #8 2023-10-13 15:43**MOT test number** 244064403311**Result** Passed**Next expiry date** 2024-10-12

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge close to wear markers (2mil) (5.2.3 (e))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2022-10-07 09:06**MOT test number** 863140078889**Result** Passed

- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #6** 2022-10-04 15:38**MOT test number** 185366499847**Result** ✗ Failed**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #5** 2021-08-16 07:20**MOT test number** 120757766920**Result** ✓ Passed**MOT #4** 2021-08-12 14:25**MOT test number** 612670479455**Result** ✗ Failed**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #3** 2021-01-07 10:26**MOT test number** 438882872123**Result** ✓ Passed**MOT #2** 2021-01-07 10:26**MOT test number** 298646839421**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid both front (3.5 (a))



MOT #1	2019-06-21 14:52
MOT test number	667737579713
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
12 October 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	12 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	VE16AZN
Plate since	2019-03-29
Current registration	VE16AZN
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-07-20
Last registration	2023-10-13
Complete history	See info



Registration #1	2016-07-20	19 mi
Registration #2	2019-06-21	34.669 mi
Registration #3	2021-01-07	46.191 mi
Registration #4	2021-01-07	46.191 mi
Registration #5	2023-10-13	46.191 mi
Registration #6	2023-10-13	46.191 mi
Registration #7	2023-10-13	46.191 mi
Registration #8	2023-10-13	46.191 mi
Registration #9	2023-10-13	46.191 mi
Registration #10	2023-10-13	46.191 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1710 kg
Max. allowed weight	2990 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M MD - C141252LWZ