





report date: 2024-03-29

General information

| Make | HYUNDAI |
|---------------------|------------------|
| Model | I30 T-GDI SE NAV |
| Colour | Brown |
| Year of manufacture | 2018 |
| Top speed | 130 mph |
| 0 - 60 mph | 8.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 138 BHP |
|-------------------------|---------------------|
| Max. torque | 242 Nm at 1.500 rpm |
| Engine capacity | 1.353 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 42.8 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 52.3 mpg |
| CO2 emission | 124 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/10



Internet history

Entry 1

Date 2021-12-05

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



MOT history

| MOT expiry date | 2024-07-30 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 8 |
| Total items failed | 0 |

| MOT #3 | 2023-07-25 14:00 |
|------------------|------------------|
| MOT test number | 651624010670 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-30 |

| MOT #2 | 2022-07-20 16:15 | |
|-----------------|---|--|
| MOT test | number 101723525679 | |
| Result | ✓ Passed | |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) | |
| Advice | Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice (a) (i)) | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #1 | | 2021-07-21 08:27 |
|----------|--|------------------|
| MOT test | number | 546237299706 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge 3mm left (5.2.3 (e)) | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge 3mm left (5.2.3 (e)) | |

CarCheck.co.uk page 3/10



Tax & MOT check



| Tax status | Valid until 1 December |
|------------------|------------------------|
| Days left | 215 |
| MOT expiry date | 30 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |
| | |

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

| , | | |
|--|-----------|------|
| For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full re | | NDAI |
| | | |
| | | |
| | | |
| | | |
| ******** | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this HYUNDAI had different number plates. | | |
| Number of plates | | , |
| Current registration | UK C | |
| Plate since | | |
| Current registration | UK C | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 7/10



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 5 |
| First mileage registration | 2018-07-31 |
| Last registration | 2023-07-25 |
| Complete history | See info |



| Registration #1 | 2018-07-31 | 18 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-07-21 | 24.688 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | | 77.777 66 |
| Registration #5 | | 11.777 es |

More info >

CarCheck.co.uk page 9/10



Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 88% |
| Children | 84% |
| Pedestrian | 64% |
| Safety systems | 68% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| Width | 1795 mm |
|---------------------|---------|
| Height | 1455 mm |
| Length | 4340 mm |
| Wheel base | 2650 mm |
| Kerb weight | 1352 kg |
| Max. allowed weight | 1820 kg |

Additional information

| Fuel tank capacity | 50 | |
|-----------------------------------|------------------|------------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 | page 10/10 |

Number of axles 2

Engine number G4LDHD097508