





report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	Blue
Year of manufacture	2014
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-11-22

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2025-02-07
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	12
Total items failed	11

MOT #12	2024-02-08 16:51
MOT test number	985486624116
Result	✓ Passed
Next expiry date	2025-02-07

MOT #11	2022-11-21 16:12
MOT test number	657413316866
Result	✓ Passed
Advice Rear Exhaust mounting defective (6.1.2 (a))	

MOT #10	2022-11-21 16:12
MOT test number	120170699346
Result	★ Failed
Advice Rear Exhaust mounting defective (6.1.2 (a))	
Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Coolant leak

Minor (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)

MOT #8 2021-08-13 11:50 **MOT** test number 883281867735 Result × Failed **Pass with rectification** Offside Headlamp aim too low (4.1.2 (a)) **Advice** Coolant leak Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Pass with rectification Nearside Headlamp aim too low and too far to the right. (4.1.2 (a)) **Advice** Rear Exhaust mounting defective (6.1.2 (a))

MOT #7	2020-08-17 11:29
MOT test number	748089426527
Result	✓ Passed

MOT #6	2019-07-26 07:51
MOT test number	491887993437
Result	✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #5 2019-07-26 07:51

MOT test number 998411967714

Result X Failed

Pass with rectification

Nearside Rear Registration plate lamp inoperative in the case of a single lamp or

all lamps (4.7.1 (b) (ii))

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #4 2018-08-06 15:34

MOT test number 417349545886

Result

Passed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2018-08-06 10:47

MOT test number 306243412922

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #2 2017-08-03 10:23

MOT test number 713012673165

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

Result

Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)

Fail Offside Rear Exhaust system not adequately supported (7.1.1)

Fail Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)

CarCheck.co.uk page 6/13



KR64HFE report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	7 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

KR64HFE

report date: 2024-03-28

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info

Plate changes

See in this check if this CITROEN had different number plates.

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-11-27
Last registration	2024-02-08
Complete history	See info



Registration #1	2014-11-27	7 mi
Registration #2	2017-08-02	28.845 mi
Registration #3	2017-08-03	28.846 mi
Registration #4	2018-08-06	47.311 mi
Registration #5	2018-08-06	47.312 mi
Registration #6	2019-07-26	75.222 mi
Registration #7	2019-07-26	75.222 mi
Registration #8		11.777 es
Registration #9		11.777 66
Registration #9 Registration #10		11.777 es
		17.777 es 17.777 es 17.777 es
Registration #10		17,777 es 17,777 es 17,777 es
Registration #10 Registration #11		77,777 es 71,777 es 71,777 es 71,777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM3167254

CarCheck.co.uk page 13/13