





report date: 2024-03-28

General information

Make	FIAT
Model	FIORINO 16V MULTIJET SX
Colour	White
Year of manufacture	2017
Top speed	100 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	76.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-03-16

Pictures 21

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-08
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	21
Total items failed	1

MOT #9	2024-01-04 17:04
MOT test number	867182835493
Result	✓ Passed
Next expiry date	2025-01-08

MOT #8		2024-01-04 11:32
MOT test	number	208547233051
Result		X Failed
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
MAJOR	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
MAJOR cords edge	Offside Front Inner Tyre has a cut in excess of the requirements deep enouge. 185/65r15 (5.2.3 (d) (i))	h to reach the ply or

MOT #7		2023-01-09 13:34
MOT test	number	866620711636
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #6 2023-01-07 10:32

MOT test number 750258935507

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Nearside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #5 2022-04-05 07:42

MOT test number 488003285644

Result ✓ Passed

MOT #4 2022-04-05 07:42

MOT test number 517541265172

Result X Failed

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #3 2020-12-15 08:53

MOT test number 175834233387

Result

Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



MAJOR

YP17NFK

report date: 2024-03-28

MOT #2 2020-12-11 11:46 695888638076 **MOT** test number Result **★** Failed **MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps Both (4.7.1 (b) (ii)) **MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii)) **MAJOR** Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i)) Advice Nearside Front Upper Mounting partially siezed **MAJOR** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i)) **DANGEROUS** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #1	2020-06-07 05:52
MOT test number	369005205938
Result	✓ Passed
Advice COVID-19 6 MONTH EXTENSION	

Front Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	8 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra FIAT salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner History	
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report \(\frac{1}{2} \)	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIX
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-06-15
Last registration	2024-01-04
Complete history	See info



Registration #1	2017-06-15	15 mi
Registration #2	2020-12-11	35.508 mi
Registration #3	2020-12-15	35.509 mi
Registration #4		11.777 es
Registration #5	2022-04-05	45.981 mi
Registration #6		11.777 ea
		11.777 ea 11.777 ea
Registration #6		11.777 es 11.777 es
Registration #6 Registration #7		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	6321333

CarCheck.co.uk page 12/12