





report date: 2024-03-29

General information

| Make | BMW |
|---------------------|-------------------|
| Model | 740 740D M SPORT |
| Colour | Grey |
| Year of manufacture | 2011 |
| Top speed | 155 mph |
| 0 - 60 mph | 6.3 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 302 BHP |
|-------------------------|---------------------|
| Max. torque | 600 Nm at 1.500 rpm |
| Engine capacity | 2.993 сс |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 31.4 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 40.9 mpg |
| CO2 emission | 181 g/km |
| CO2 label | 1 |



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-09


Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

| MOT expiry date | 2023-08-10 |
|--------------------|------------|
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 21 |
| Total items failed | 2 |

| MOT #11 | | 2022-08-11 12:42 |
|-----------|--|------------------|
| MOT test | number | 546102882545 |
| Result | | ✓ Passed |
| Next expi | ry date | 2023-08-10 |
| Advice | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) | |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #10 | 2021-08-10 11:17 |
|--|------------------|
| MOT test number | 857323057729 |
| Result | ✓ Passed |
| | |
| MOT #9 | 2020-08-06 11:56 |
| MOT test number | 533961009251 |
| Result | ✓ Passed |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Nearside Rear Nail in tyre | |

CarCheck.co.uk page 3/12



MOT #8 2020-08-06 10:31

MOT test number 944687029373

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Nail in tyre

Fail Offside Rear Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Nail in tyre

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2019-04-02 08:45

MOT test number 965315412895

Result ✓ Passed

MOT #6 2018-04-10 08:54

MOT test number 603574133914

Result

Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Nail in tyre

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

Advice

Offside Rear Nail in tyre

Fail

Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2017-04-05 09:05 **MOT** test number 640916288417 Result ✓ Passed **MOT** #3 2016-11-21 09:54 869406043035 **MOT** test number Result ✓ Passed **Advice** Both rear tyres wearing on inner edge of tread **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT test number

Result

Advice Child seat fitted at time of test not allowing full inspection on seatbelt

Windscreen has damage but not in swept area

 MOT #1
 2014-12-02 09:40

 MOT test number
 938696334342

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check

Tax expired: 1 October 2022



Expired: 10 August 2023 X MOT

| Tax status | Expired at 1 October 2022 |
|------------------|---------------------------|
| Days left | 575 days too late |
| MOT expiry date | 10 August 2023 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| | 1 |
| Band | ı |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

| For how long did the current and previous owner(s) have this BMW? How many owners declared the full report and see all owner registrations. Download the full report and see all owner registrations. | |
|---|-------------|
| | |
| | |
| | |
| *************************************** | |
| | |
| *************************************** | |
| ************ | |
| | |
| | More info > |
| | |
| Plate changes | |
| See in this check if this BMW had different number plates. | |
| Number of plates | |
| Current registration | UK UK |
| Plate since | |
| Current registration | NK NK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2011-11-29 |
| Last registration | 2022-08-11 |
| Complete history | See info |



| Registration #1 | 2011-11-29 | 25 mi |
|------------------|------------|-----------|
| Registration #2 | 2014-12-02 | 21.050 mi |
| Registration #3 | 2015-11-17 | 33.609 mi |
| Registration #4 | 2016-11-21 | 49.300 mi |
| Registration #5 | 2017-04-05 | 50.476 mi |
| Registration #6 | 2018-03-28 | 73.839 mi |
| Registration #7 | 2018-04-10 | 74.540 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 0.00 44 |
| Registration #13 | | 10.777 au |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1902 mm |
|---------------------|---------|
| Height | 1488 mm |
| Length | 5072 mm |
| Wheel base | 3210 mm |
| Kerb weight | 1950 kg |
| Max. allowed weight | 2505 kg |

Additional information

| Fuel tank capacity | 80 I | |
|-----------------------------------|------------------|------------|
| Fuel delivery | Direct Injection | |
| Number of doors | 4 | |
| Number of seats CarCheck.co.uk | 5 | page 12/12 |

Number of axles 2
Engine number 35417619