





report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	E E 220 D AMG LINE EDITION
Colour	White
Year of manufacture	2016
Top speed	145 mph
0 - 60 mph	8.1 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-02

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2025-01-10
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	8
Total items failed	4

MOT #8	2024-01-10 09:35
MOT test number	293032193446
Result	✓ Passed
Next expiry date	2025-01-10
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #7		2023-01-05 14:34
MOT test	number	800442691154
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Wheel bearing has slight play Both (5.1.3 (a) (i))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6	2022-01-11 14:10
MOT test number	505810571932
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #5 2021-01-08 11:33

MOT test number 181367287528

Result ✓ Passed

MOT #4 2020-09-12 11:40

MOT test number 730029146581

Result

Passed

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #3 2020-09-11 14:02

MOT test number 608821650127

Result X Failed

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #2 2019-09-30 13:41

MOT test number 338685363678

Result

Passed

MOT #1 2019-09-30 09:09

MOT test number 173324876083

Result X Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check





Tax expired: 4 April 2024

Tax status	Expired at 4 April 2024
Days left	25 days too late
MOT expiry date	10 January 2025
Full MOT history	See MOT history

Expires: 10 January 2025

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Type

Damage 2
Date

Category

Type



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How may MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK OK
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-30
Last registration	2024-01-10
Complete history	See info



Registration #1	2016-09-30	28 mi
Registration #2	2019-09-30	39.887 mi
Registration #3	2019-09-30	39.887 mi
Registration #4	2020-09-11	48.373 mi
Registration #5	2020-09-12	48.373 mi
Registration #6		71.777 es
Registration #6 Registration #7		11.77 es
-		1.77 m
Registration #7		11.77 es 11.77 es 11.77 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

60225	Air conditionin
60295	
0482	
0501	
0566	
0567	
0569	
iew the complete MERCEDES-BENZ factory list for this	More info >

Dimensions & weight

Width	1786 mm
Height	1397 mm
Length	4703 mm
Wheel base	2760 mm
Kerb weight	1735 kg
Max. allowed weight	2205 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	65191133356554

CarCheck.co.uk page 11/11