





report date: 2024-03-28

General information

Make	BMW
Model	630 630I SPORT
Colour	Black
Year of manufacture	2007
Top speed	155 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	255 BHP
Max. torque	300 Nm at 2.500 rpm
Engine capacity	2.996 сс
Cylinders	6
Fuel type	Petrol
Consumption city	20.3 mpg
Consumption extra urban	40.4 mpg
Consumption combined	29.7 mpg
CO2 emission	226 g/km
CO2 label	L



CarCheck.co.uk page 1/12



report date: 2024-03-28


Internet history


Entry 1

Date 2021-05-28

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-11-14
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	22
Total items failed	3

MOT #15		2023-11-14 11:12
MOT test num	nber	769031895189
Result		✓ Passed
Next expiry da	ate	2024-11-14
Advice Ne	earside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement Front inner (5.3.4 (a) (i))		
Advice Off	fside Front Nail in tyre	
Advice Off	fside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Off Front inner (5.3	fside Rear Lower Suspension arm pin or bush worn but not resulting in excess 3.4 (a) (i))	sive movement

MOT #14		2022-11-12 12:17
MOT test	number	498951849126
Result		✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement Inner front (5.3.4 (a) (i))		
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Inner fron	Nearside Rear Lower Suspension arm pin or bush worn but not resulting in ϵ t (5.3.4 (a) (i))	excessive movement

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #13	2021-11	-15 15:07
MOT test	number 6247	40717831
Result		✓ Passed
Advice	Fuel cap seal perished but still forming a good seal	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing Slight damage to inner sidewall (5.2.3 (d) (ii))		
Advice	Rear Coil spring corroded Both (5.3.1 (b) (i))	
Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement All bushes in both arms (5.3.4 (a) (i))		

MOT #12	2020-11-05 15:22
MOT test number	543297283139
Result	✓ Passed
MOT #11	2019-11-12 09:55
MOT test number	147396848042
Result	✓ Passed
MOT #10	2018-11-15 10:52
MOT test number	336886291794
Result	✓ Passed
MOT #9	2018-01-16 11:03
MOT toot number	271556200066

1101 #3	2010-01-10 11.03
MOT test number	271556308966
Result	✓ Passed

CarCheck.co.uk page 4/12



MOT test number

EN07XCS

report date: 2024-03-28

906873515028

MOT test number

Result

Advice Offside Rear Upper Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Offside Front tyre wearing on edge

Advice Both rear tyres wearing on inner edge

MOT #7

MOT test number

434034436140

Result

Advice Offside Rear nail in tyre

Advice Offside Rear Upper Suspension arm has slight play in a ball joint rear ball joint slight play (2.4.G.2)

MOT #6

MOT test number

Result

MOT #5

2015-01-13 16:13

148193315485

✓ Passed

Result × Failed

Fail Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #4

MOT test number

2014-01-14 12:16

MOT test number

225954314034

Result

✓ Passed

Advice

Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT #3		2013-01-16 16:04
MOT test	number	417966513080
Result		✓ Passed
MOT #2		2012-01-26 12:13
MOT test	number	166246222021
Result		✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	O/S/R tyre worn on inner edge	
Notice	Both front tyres worn on inner and outer edges	

MOT #1	2010-06-07 09:21
MOT test number	153088450165
Result	✓ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	14 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 7/12



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



Owner history

EN07XCS

report date: 2024-03-28

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-06-28
Last registration	2023-11-14
Complete history	See info



Registration #1	2007-06-28	14 mi
Registration #2	2010-06-07	33.423 mi
Registration #3	2012-01-26	65.289 mi
Registration #4	2013-01-16	83.059 mi
Registration #5	2014-01-14	100.765 mi
Registration #6	2015-01-13	116.822 mi
Registration #7	2015-01-13	116.823 mi
Registration #8	2016-01-12	132.444 mi
Registration #9	2017-01-16	148.979 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		71,777 66
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1373 mm
Length	4820 mm
Wheel base	2780 mm
Kerb weight	1510 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine number07726504