



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA HDI DESIRE 2 PICASSO
Colour	Beige
Year of manufacture	2004
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.900 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	147 g/km
CO2 label	F





MOT history

MOT expiry date	2021-10-28
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	24
Total items failed	43

MOT #22	2020-10-22 15:36
MOT test number	712557324488
Result	✓ Passed
Next expiry date	2021-10-28

MOT #21	2019-04-29 16:11
MOT test number	708655307849
Result	✓ Passed

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #20**

2019-04-26 09:14

MOT test number

782054806330

Result**✗ Failed**

Fail Nearside Rear Brake pipe excessively corroded THATB RUN S THE FRONT LIKELY TO BURST CORRDED AT MOUNTAIN CLIPS (1.1.11 (c))

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a))

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Fail Offside Front Side repeater incorrect colour (4.4.3 (a))

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Front Inner Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Front Position lamp not working (4.2.1 (a))

**MOT #19**

2019-04-15 11:37

MOT test number

281685709329

Result

✗ Failed

- Fail** Windscreen damaged and affecting the driver's view of the road cracked windscreen and swept marks nearside (3.2 (a) (ii))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Fail** Offside Side repeater incorrect colour (4.4.3 (a))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Corrosion to brake and suspension components

MOT #18

2018-04-10 10:06

MOT test number

314420999186

Result

✓ Passed

- Advice** Offside Front Lower Ball joint has slight play (2.2.B.1f)

MOT #17

2017-04-05 15:07

MOT test number

584090794499

Result

✓ Passed

- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #16**

2016-03-29 15:39

MOT test number

207716962255

Result

✓ Passed

Advice Offside Front Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Exhaust has a minor leak of exhaust gases back box corroded (7.1.2)

Advice Nearside Front Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit void on outer edge (4.1.E.1)

MOT #15

2016-03-23 15:34

MOT test number

715243256089

Result

✗ Failed

Advice Exhaust has a minor leak of exhaust gases back box corroded (7.1.2)

Fail Offside Side repeater incorrect colour (1.4.A.2f)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Front Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit void on outer edge (4.1.E.1)

Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Front Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #14

2015-03-30 16:47

MOT test number

599489485012

Result

✓ Passed

**MOT #13** 2015-03-25 10:27**MOT test number** 727734485043**Result** ✗ Failed

- Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Rear Body has a sharp edge caused by damage (6.1.C.1)
- Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Stop lamp not working (1.2.1b)

MOT #12 2014-03-26 15:29**MOT test number** 307025684038**Result** ✓ Passed

- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT #11 2014-03-26 11:43**MOT test number** 995225684071**Result** ✗ Failed

- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #10 2013-03-27 16:26**MOT test number** 247916283051**Result** ✓ Passed

- Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

**MOT #9** 2013-03-27 16:26**MOT test number** 406066183099**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2012-03-30 12:01**MOT test number** 119400192045**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2011-03-23 15:28**MOT test number** 545762281071**Result** ✓ Passed**MOT #6** 2011-03-23 12:00**MOT test number** 837702281002**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #5** 2010-03-26 15:06**MOT test number** 630115480011**Result** ✓ Passed**MOT #4** 2010-03-26 12:37**MOT test number** 350705080017**Result** ✗ Failed

- Fail** Offside Headlamp not working on dipped beam (1.7.5a)
- Fail** Rear Exhaust system not adequately supported (7.1.1)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #3 2009-03-30 14:21**MOT test number** 880889089015**Result** ✓ Passed**MOT #2** 2008-03-28 12:07**MOT test number** 991138588031**Result** ✓ Passed

- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT #1 2007-03-28 11:47**MOT test number** 182617587056**Result** ✓ Passed



Tax & MOT check

×

Untaxed

Tax expired:
17 December 2020

×

MOT

Expired:
28 October 2021

Tax status

Expired at 17 December 2020

Days left

1229 days too late

MOT expiry date

28 October 2021

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-03-25
Last registration	2020-10-22
Complete history	See info



Registration #1	2004-03-25	18 mi
Registration #2	2007-03-28	37.499 mi
Registration #3	2008-03-28	47.392 mi
Registration #4	2009-03-30	55.591 mi
Registration #5	2010-03-26	62.935 mi
Registration #6	2010-03-26	62.935 mi
Registration #7	2011-03-23	70.373 mi
Registration #8	2011-03-23	70.373 mi
Registration #9	2012-03-30	78.642 mi
Registration #10	2013-03-27	86.844 mi
Registration #11	2014-03-26	94.562 mi
Registration #12	2015-03-26	102.280 mi
Registration #13	2016-03-26	110.000 mi
Registration #14	2017-03-26	117.720 mi
Registration #15	2018-03-26	125.440 mi
Registration #16	2019-03-26	133.160 mi
Registration #17	2020-03-26	140.880 mi
Registration #18	2021-03-26	148.600 mi
Registration #19	2022-03-26	156.320 mi
Registration #20	2023-03-26	164.040 mi
Registration #21	2024-03-26	171.760 mi
Registration #22	2025-03-26	179.480 mi

More info >



Safety ratings

NCAP rating



Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Engine number	DYRZ4017511