



report date: 2024-03-28

General information

Make	CITROEN
Model	C4 GRAND PICASSO GRAND BLUEHDI FLAIR S/S EAT6
Colour	Blue
Year of manufacture	2017
Top speed	129 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	370 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-29
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-02-10
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	7
Total items failed	9

MOT #8	2024-02-06 14:37
MOT test number	234686632666
Result	✓ Passed
Next expiry date	2025-02-10

MOT #7	2024-01-31 11:00
MOT test number	392229577718
Result	✗ Failed
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt boot split (6.1.7 (g) (ii))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt boot split (6.1.7 (g) (ii))

MOT #6	2023-02-11 13:41
MOT test number	889326750178
Result	✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #5** 2023-02-09 15:08**MOT test number** 865994246902**Result** ✗ Failed**Fail** Offside Headlamp aim too low (4.1.2 (a))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #4** 2022-01-17 11:29**MOT test number** 988406094156**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #3** 2020-12-16 16:54**MOT test number** 804531974599**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear brake discs corroded and pitted on surfaces (1.1.14 (a) (ii))**MOT #2** 2020-12-16 16:54**MOT test number** 450683889283**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear brake discs corroded and pitted on surfaces (1.1.14 (a) (ii))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))



MOT #1	2020-01-16 14:04
MOT test number	800522745782
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
10 February 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	10 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-03-24
Last registration	2024-02-06
Complete history	See info



Registration #1	2017-03-24	18 mi
Registration #2	2020-01-16	27.229 mi
Registration #3	2020-12-16	30.416 mi
Registration #4	2020-12-16	30.416 mi
Registration #5	2020-01-16	27.229 mi
Registration #6	2020-01-16	27.229 mi
Registration #7	2020-01-16	27.229 mi
Registration #8	2020-01-16	27.229 mi
Registration #9	2020-01-16	27.229 mi
Registration #10	2020-01-16	27.229 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1826 mm
Height	1644 mm
Length	4597 mm
Wheel base	2840 mm
Kerb weight	1476 kg
Max. allowed weight	2280 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DZAH4010506