



RENAULT

Y244WRH

report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO AUTHENTIQUE
Colour	Silver
Year of manufacture	-
Top speed	95 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	114 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.7 mpg





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT #21	2022-02-07 10:15
MOT test number	713096637738
Result	✓ Passed
Next expiry date	2023-02-06
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Nearside Rear Shock absorbers has light misting of oil rear of 2 (5.3.2 (b))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #20	2020-09-03 15:42
MOT test number	363319229011
Result	✓ Passed

MOT #19	2019-05-31 11:07
MOT test number	506779072557
Result	✗ Failed
Advice	Nearside Front Vehicle structure is deformed but structural rigidity is not significantly reduced outrigger deformed car been jacked up on it (6.1.1 (a) (i))
Fail	Supplementary restraint system warning lamp indicates a fault air bag light on (7.1.6 (a))
Advice	Cooling fan for engine not working emissions stopped due to engine temperature too high
Fail	Emissions not tested test stopped lambda readings too high (8.2.1.2 (d))
Fail	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt spilt (6.1.7 (g) (ii))
Minor	Offside Obligatory mirror slightly damaged door mirror cracked still functional (3.3 (b) (i))

MOT #18	2018-03-16 10:13
MOT test number	610920857158
Result	✓ Passed

MOT #17	2017-06-27 15:25
MOT test number	603316794986
Result	✓ Passed

**MOT #16**

2016-07-19 09:59

MOT test number

805533124245

Result

✓ Passed

Advice

Oil leak

MOT #15

2015-07-14 12:42

MOT test number

486535995154

Result

✓ Passed

Notice

Oil leak

MOT #14

2015-07-14 12:42

MOT test number

959515195151

Result

✗ Failed

Notice

Oil leak

Pass with rectification

Offside Front position lamp(s) not working (1.1.A.3b)

MOT #13

2014-07-22 16:18

MOT test number

397493504219

Result

✓ Passed

Advice

Offside Front Track rod end ball joint has slight play (2.2.B.1f)

Notice

Oil leak

Advice

Front Exhaust has a minor leak of exhaust gases (7.1.2)

Advice

Offside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #12**

2014-07-22 09:11

MOT test number

379243804291

Result**✗ Failed****Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Oil leak**MOT #11**

2013-07-25 09:24

MOT test number

246966503214

Result**✓ Passed****Advice** Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Offside Front coil spring corroded (2.4.C.1b)**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Steering rack gaiter deteriorated (2.2.D.2d)

**MOT #10** 2012-07-20 08:46**MOT test number** 317012902276**Result** ✓ Passed**MOT #9** 2012-07-18 18:26**MOT test number** 798900302246**Result** ✗ Failed

Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Fail Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

MOT #8 2011-07-25 16:21**MOT test number** 547436901218**Result** ✓ Passed

Advice Brake pipe slightly corroded (3.6.B.2c)

Advice Centre Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front coil spring corroded (2.4.C.1b)

Advice Rear Exhaust has part of the system slightly deteriorated (7.1.1a)

Advice Nearside Steering rack gaiter deteriorated (2.2.D.2d)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #7 2011-07-25 12:19

MOT test number 976616801257

Result ✗ Failed

- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)
- Advice** Nearside Steering rack gaiter deteriorated (2.2.D.2d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6 2010-07-23 14:06

MOT test number 783814600263

Result ✓ Passed

- Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)
- Advice** Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)
- Advice** Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Advice** Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5**

2010-07-15 14:03

MOT test number

661446990117

Result

✗ Failed

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Service brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Fail** Brake pipe excessively corroded (3.6.B.2c)**Advice** Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Advice** Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4**

2009-07-14 16:59

MOT test number

160875399156

Result

✓ Passed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #3**

2008-07-17 12:55

MOT test number

591629398158

Result

✓ Passed

MOT #2

2007-05-18 15:17

MOT test number

431948237137

Result

✓ Passed

Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)



MOT #1	2006-04-27 16:50
MOT test number	251377616408
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	Y244WRH
Plate since	2024-03-28
Current registration	Y244WRH
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2001-04-01
Last registration	2022-02-07
Complete history	See info



Registration #1	2001-04-01	11 mi
Registration #2	2006-04-27	10.694 mi
Registration #3	2007-05-18	16.281 mi
Registration #4	2008-07-17	21.637 mi
Registration #5	2009-07-14	26.778 mi
Registration #6	2010-07-15	31.222 mi
Registration #7	2010-07-23	31.265 mi
Registration #8	2011-07-25	35.234 mi
Registration #9	2011-07-25	35.234 mi
Registration #10	2012-07-18	38.675 mi
Registration #11	2012-07-20	38.675 mi
Registration #12	2013-07-20	42.116 mi
Registration #13	2014-07-20	45.557 mi
Registration #14	2015-07-20	49.000 mi
Registration #15	2016-07-20	52.443 mi
Registration #16	2017-07-20	55.886 mi
Registration #17	2018-07-20	59.329 mi
Registration #18	2019-07-20	62.772 mi
Registration #19	2020-07-20	66.215 mi
Registration #20	2021-07-20	69.658 mi
Registration #21	2022-02-07	73.101 mi
Registration #22	2022-02-07	73.101 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2060 mm
Height	1827 mm
Length	3995 mm
Wheel base	2600 mm
Kerb weight	1065 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	R116866