





report date: 2024-03-28

General information

Make	FORD
Model	FUSION
Colour	Silver
Year of manufacture	2003
Gearbox	-

Engine & fuel consumption

Engine capacity	1.596 cc
Fuel type	Petrol
CO2 emission	160 g/km
CO2 label	G



CarCheck.co.uk page 1/15



Internet history

Entry 1

Date 2021-07-03

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-12-13
MOT pass rate	86 %
MOT passed	18
Failed MOT tests	3
Total advice items	40
Total items failed	5

MOT #21		2023-12-14 12:08
MOT test number		457081875522
Result		✓ Passed
Next expiry date		2024-12-13
Advice Nearsion	de Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside	e Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Front E	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #20		2022-08-23 09:42
MOT test	number	402252813337
Result		✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases and rear (6.1.2 (a))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT test number

607708029610

Result

Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18

MOT test number

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT test number
600606864581

Result
✓ Passed

Minor
Front Lower Suspension arm ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))

Advice
Rear Exhaust has a minor leak of exhaust gases joint (6.1.2 (a))

Minor
Headlamp lens slightly defective both (4.1.1 (b) (i))

CarCheck.co.uk page 4/15



report date: 2024-03-28

✓ Passed

MOT #16 2018-10-02 15:52

MOT test number 804188696215

Result ✓ Passed

Advice Rear exh slightly deteriorated.

Advice Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

Advice Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

MOT #15 2018-10-01 15:38

MOT test number 726828560736

Result X Failed

Advice Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

Advice Rear exh slightly deteriorated.

Result

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #14 2017-10-24 13:58

MOT test number 321722373428

321,223,312

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/15



MOT #13 2017-10-24 09:28

MOT test number 701680624882

Result X Failed

Fail Offside Rear Rear wheel bearing rough when rotated (2.6.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #12 2016-10-19 14:06

MOT test number 194598614577

Result ✓ Passed

Advice Nearside Rear dust cover slightly deteriorated.

MOT #11 2016-10-19 14:06

MOT test number 771848897645

Result × Failed

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Rear dust cover slightly deteriorated.

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #10 2015-10-23 08:34

MOT test number 193974524732

Result
✓ Passed

MOT #9 2014-10-28 17:57

MOT test number 379201204318

Result ✓ Passed

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT test number

Result

Advice Power steering component(s) has slight seepage from a component (2.3.3b)

Notice Both headlamp lenses slightly deteriorated.

Notice Oil leak

MOT #7 2013-05-22 17:00 **MOT** test number 736522443136 Result ✓ Passed **Notice** Front wiperblades slightly worn. Notice O/S/F + O/S/R tyres 2-3mm + o/s/r tyre slightly perished. Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Notice Both headlamp lenses discoloured. Notice N/S/R tyre 3mm + slightly perished.

 MOT #6
 2012-05-09 12:33

 MOT test number
 987650032167

 Result
 ✓ Passed

 Notice
 Tyres worn.

 MOT #5
 2011-05-24 14:51

 MOT test number
 205764141165

 Result
 ✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #4		2010-05-26 13:00
MOT test	number	270806440175
Result		✓ Passed
Notice	O/S/R tyre 2.5mm + slightly perished.	
Notice	Front wiperblades worn.	
Notice	N/S/R tyre slightly perished.	

typy type originally posterious	
MOT #3	2009-06-08 10:56
MOT test number	641469359131
Result	✓ Passed
MOT #2	2007-09-13 15:36
MOT test number	344236257413
Result	✓ Passed
MOT #1	2006-09-16 12:11
MOT test number	443379956228
Result	√ Passed

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	13 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

e union mestery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes See in this check if this FORD had different number plates.	
Number of plates	,
Correct registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-09-01
Last registration	2023-12-14
Complete history	See info



Registration #1	2003-09-01	20 mi
Registration #2	2006-09-16	23.419 mi
Registration #3	2007-09-13	34.999 mi
Registration #4	2009-06-08	45.426 mi
Registration #5	2010-05-26	49.339 mi
Registration #6	2011-05-24	51.585 mi
Registration #7	2012-05-09	54.395 mi
Registration #8	2013-05-22	58.011 mi
Registration #9	2014-05-28	61.248 mi
Registration #10	2014-10-28	62.980 mi
Registration #11	2015-10-23	73.359 mi
Registration #12	2016-10-19	83.374 mi
Registration #12	2010-10-19	05.57 + 1111
Registration #13	2010-10-19	03.374 1111
-		03.374 1111
Registration #13		03.374 1111
Registration #13 Registration #14		03.374 1111
Registration #13 Registration #14 Registration #15		03.374 1111
Registration #13 Registration #14 Registration #15 Registration #16		03.374 1111
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		03.374 1111
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		03.374 1111
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		03.374 1111
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		03.374 IIII
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		03.3741111

More info >

CarCheck.co.uk page 14/15



Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Additional information

Engine number 3E09767

CarCheck.co.uk page 15/15