



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	AURIS DUAL VVT-I ICON
Colour	Red
Year of manufacture	2015
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	128 Nm at 3.800 rpm
Engine capacity	1.329 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-07-12
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #8	2023-07-07 16:48
MOT test number	570108746442
Result	✓ Passed
Next expiry date	2024-07-12
Advice	Both n/s and o/s/f bottom suspension arms corroding

MOT #7	2023-07-07 11:27
MOT test number	362490708078
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Both n/s and o/s/f bottom suspension arms corroding
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #6	2022-07-05 13:17
MOT test number	438169307771
Result	✓ Passed
Advice	Slight play in offside of steering rack
Advice	Nearside rear tyre outer side wall slightly perished and cracking

**MOT #5** 2021-07-13 14:35**MOT test number** 984577280789**Result** ✓ Passed**MOT #4** 2020-10-21 08:07**MOT test number** 834465257657**Result** ✓ Passed**MOT #3** 2019-05-08 15:15**MOT test number** 217095773757**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front has small cut in outer tyre wall**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2019-05-08 09:48**MOT test number** 866093011574**Result** ✗ Failed**Advice** Nearside Front has small cut in outer tyre wall**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #1** 2018-04-26 14:20**MOT test number** 582719979863**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
12 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	12 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-06-30
Last registration	2023-07-07
Complete history	See info



Registration #1	2015-06-30	10 mi
Registration #2	2018-04-26	13.435 mi
Registration #3	2019-05-08	23.558 mi
Registration #4	2019-05-08	23.558 mi
Registration #5	2020-10-21	38.833 mi
Registration #6	2022-05-20	55.277 mi
Registration #7	2022-05-20	55.277 mi
Registration #8	2022-05-20	55.277 mi
Registration #9	2022-05-20	55.277 mi
Registration #10	2023-07-07	55.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	68%
Safety systems	66%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1390 mm
Length	4275 mm
Wheel base	2600 mm
Kerb weight	1235 kg
Max. allowed weight	1735 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1NR0770040