



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-12-16
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-15
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	19
Total items failed	8

MOT #15	2023-11-16 17:33
MOT test number	329457159564
Result	✓ Passed
Next expiry date	2024-11-15
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #14	2023-11-16 09:51
MOT test number	972968365029
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing cracks on inner side wall (5.2.3 (d) (ii))
Fail	Offside Front Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2.7mm (5.2.3 (e))

MOT #13	2022-10-25 11:09
MOT test number	131889501763
Result	✓ Passed
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge slight inner edge wear (5.2.3 (e))

**MOT #12** 2021-11-04 16:27**MOT test number** 482745510060**Result** ✓ Passed**MOT #11** 2021-04-20 10:37**MOT test number** 528600091605**Result** ✓ Passed**MOT #10** 2020-04-17 09:39**MOT test number** 580817839210**Result** ✓ Passed**MOT #9** 2019-04-29 09:57**MOT test number** 355488786729**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Corrosion of suspension components
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #8 2018-04-30 08:51**MOT test number** 450412142014**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2017-04-19 07:46**MOT test number** 196241975974**Result** ✓ Passed**Advice** Car as under trays**Advice** Nearside Rear Inner tyre tread edge worn**MOT #6** 2016-04-15 13:24**MOT test number** 387551719545**Result** ✓ Passed**MOT #5** 2016-04-15 09:00**MOT test number** 573651056497**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit on limit (4.1.E.1)**MOT #4** 2015-04-16 09:45**MOT test number** 256016205472**Result** ✓ Passed**MOT #3** 2015-04-16 09:45**MOT test number** 535726505152**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Headlamp aim too low (1.8)



MOT #2	2014-03-31 08:45
MOT test number	678010994082
Result	✓ Passed
<div>Notice Under-trays fitted obscuring some underside components</div>	

MOT #1	2013-04-13 10:58
MOT test number	836533903114
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
15 November 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	15 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YY10FFP
Plate since	2024-03-28
Current registration	YY10FFP
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-04-19
Last registration	2023-11-16
Complete history	See info



Registration #1	2010-04-19	14 mi
Registration #2	2013-04-13	27.531 mi
Registration #3	2014-03-31	36.764 mi
Registration #4	2015-04-16	43.550 mi
Registration #5	2016-04-15	51.058 mi
Registration #6	2016-04-15	51.058 mi
Registration #7	2017-04-19	55.537 mi
Registration #8	2018-04-30	62.825 mi
Registration #9	2019-04-20	69.277 mi
Registration #10	2020-04-20	75.277 mi
Registration #11	2021-04-20	81.277 mi
Registration #12	2022-04-20	87.277 mi
Registration #13	2023-04-20	93.277 mi
Registration #14	2024-04-20	99.277 mi
Registration #15	2025-04-20	105.277 mi
Registration #16	2026-04-20	111.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	957553