



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	White
Year of manufacture	2015
Top speed	108 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-05-26
Pictures	1
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-11-09
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	19
Total items failed	10

MOT #10	2023-11-07 17:31
MOT test number	312686548777
Result	✓ Passed
Next expiry date	2024-11-09

MOT #9	2023-11-07 09:57
MOT test number	951808543719

Result	✗ Failed
---------------	----------

- Fail** Nearside Rear Inner Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Central Front Inner Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Offside Rear Inner Service brake binding but not excessively (1.2.1 (f))
- Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Central Front Upper Windscreen washer not working (3.5 (a))

MOT #8	2022-11-09 13:05
MOT test number	867942235521

Result	✓ Passed
---------------	----------

- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #7** 2022-11-09 13:05**MOT test number** 547574269407**Result** ✗ Failed**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #6** 2021-11-10 14:07**MOT test number** 447456595159**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MOT #5** 2020-11-06 17:46**MOT test number** 190309577098**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Central Rear unable to check seat belt for dog guard preventing access.

**MOT #4** 2020-11-02 11:41**MOT test number** 780518536498**Result** ✗ Failed**Fail** Nearside Rear Seat belt damaged seat belt cut on webbing. (7.1.2 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Central Rear unable to check seat belt for dog guard preventing access.**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #3** 2019-05-28 09:24**MOT test number** 923121254964**Result** ✓ Passed**MOT #2** 2018-05-28 13:38**MOT test number** 738290763629**Result** ✓ Passed**MOT #1** 2018-05-25 11:31**MOT test number** 419683358133**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened scored (1.1.14 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
9 November 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	9 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	BT15XZX
Plate since	2015-03-29
Current registration	BT15XZX
Plate since	2015-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-05-30
Last registration	2023-11-07
Complete history	See info



Registration #1	2015-05-30	13 mi
Registration #2	2018-05-25	24.261 mi
Registration #3	2018-05-28	24.261 mi
Registration #4	2019-05-28	34.566 mi
Registration #5	2020-11-02	47.096 mi
Registration #6	2020-11-06	47.096 mi
Registration #7	2023-11-07	55.277 mi
Registration #8	2023-11-07	55.277 mi
Registration #9	2023-11-07	55.277 mi
Registration #10	2023-11-07	55.277 mi
Registration #11	2023-11-07	55.277 mi
Registration #12	2023-11-07	55.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDFZ373482